

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	3	1	3	1	3	0	0	
	Grand Total	1082	6468	1	4	1	4	1	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Huzurnagar	Singaram	11KV	Huzurnagar	09.30	11.30	02.00	E/L	11KV Jumper cut	-
2		Eduloor	G.B.Gudem	11KV	Nalgonda	07.10	09.50	02.40	E/L	11KV Jumper cut	-
3		CH.Chennaram	Thotavarigudem	11KV	Nalgonda	15.50	16.40	00.50	E/L	11KV Insulator failure	-
1	RR E	Yapral	Tulasi Garden	11KV	Sainikpuri	05.20	06.55	01.35		11Kv polymer disk failed at Jupally Homes (AE)	-

TSSPDCL - LMRC / Corporate office

Date: 25.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Kodur	33kv	Mahabubnagar	07.05	10.47	03.42	EL	33KV Pole damaged at Bandamidipally	Kodur	-