

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	2	2	2	2	2	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	132KV Medchal	33KV Keshavaram	33KV	Medchal	14.08	15.21	01.13		33KV UG Cable failed at Ravalkole	33KV Keshavaram	-
1	HYD N	132KV Jubilee Hills	Hitech City	33KV	Kalyan Ngr	07.38	07.42	00.04	EL	Isolated Shilparamam Line AB Switch, Partial fdr charged	Hitech City	-

TSSPDCL - LMRC / Corporate office

Date: 26.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole K	Bheemaram	11KV	Nalgonda	09.00	11.10	02.10	EL	11KV lline Jumpe Cut	-
2		G.Yedavelly	Lingalagudem	11KV	Nalgonda	06.00	09.00	03.00	EL	11KV lline Insulator Fail	-
3		Dirsenapally	Alugunooru	11KV	Suryapet	14.30	16.20	01.50	EL	Insulator flashover	-
4		Huzurnagar	Singaram	11KV	Huzurnagar	09.30	11.30	02.00	EL	11 KV Jumper cut	-
5		Chamapur	Chandapally	11KV	Bhongir	04.00	09.25	05.25	EL	11kv Jumper Cut & 11kv Insulator Fail ss 2 Chandapally Village	-
6		Peddakandukur	Peddakandukur	11KV	Bhongir	10.30	15.00	04.30	EL	11kv Pole Damaged In Sub-Stastion near	-
1	RR E	Moulla-Ali	Kailasagiri	11KV	Sainikpuri	16.57	17.35	00.38		Lezard fallen on 11Kv line at Alluri Sitharama Raju Stachu (AE/OP)	-
2		VP Nagar	Officers Colony	11KV	Sainikpuri	12.00	13.12	01.12		11Kv Over Head Cable Kit failure at SS Yard (LM Narsimma)	-