

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	5	2	5	2	5	0	0	
	Grand Total	1082	6468	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.11.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Sri Rangapur	Kondurgu	33KV	Shadnagar	05.25	07.10	01.45	E/L	Insulator Failure at Kondurgu	Kondurgu	No
1	NLG	Marriguda	Chandur	33KV	Nalgonda	4:30	9:50	5:20		33KV line slipped from 33KV insulator at near 132KV SS Marriguda	Chandur	No

TSSPDCL - LMRC / Corporate office

Date: 28.11.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mothiganpur	Mothiganpur	11KV	Jadcherla	05.10	10.20	05.10		11KV Wire Cut Near Narsi Reddy Land at Mothiganpur (V)	No
1	NLG	Reddygudem	Reddygudem	11KV	Suryapet	8:05	10:30	2:25	EL	Insulator flashover	No
2		Janpahad	Shunyapahad	11KV	Huzurnagar	09.20	11.30	02.10	EL	11KV Line snapped	No
3		Gondiryala	Chimiryala	11KV	Huzurnagar	04.00	06.30	02.30	EL	11KV Line snapped	No
1	MDK	Krishnapur	Khanapur	11KV	Jogipet	6:30	9:00	2:30		Jumper cut near Khanapur (V)	No
1	RR S	ESCI	Nanakramguda	11KV	Gachibowli	1:30	2:40	1:10		11KV UG Cable Damaged near Pakwaan Hotel Karkhana.	No
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	9:40	11:30	1:50		Tree fallen on the 11KV Line at VRL Company Backside	No
1	HYD N	Road No.22	UCO Bank	11KV	Jublee Hills	05.55	07.15	01.20	All Indication	Cable fault at Road No.10 (2No. DTR's kept off)	No
2		Raheja	Building No.8	11KV	Jublee Hills	9:25	15:15	5:50	All Indication	CT flash over at Building No.8	No