

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thrukapally	Thurkapaly	11KV	Nalgonda	11.50	14.48	02.58	EL	11 KV Line Insulator Fialure	-
2		Aregudem	Chityala AGL	11KV	Nalgonda	10.55	13.30	02.35	EL	11 KV Line Jumper Cut	-
3		Adivemla	Thimmapuram	11KV	Suryapet	09.30	12.00	02.30	EL	Insulator flashover	-
4		Ananthagiri	V.R.Puram	11KV	Huzurnagar	02.30	06.00	03.30	EL	Due to Jumper open	-
1	MDK	Aligole	Aligole	11KV	Zaheerabad	05.30	09.50	04.20		BD due to Insulator failed	-
2		Satwar	Cherakpally	11KV	Zaheerabad	09.32	12.45	03.13		BD due to Insulator failed	-
1	RR E	Saketh	Pranam	11KV	Sainikpuri	10.58	11.33	00.35		11Kv UG Cable Straight Thru Joint line failure at Swarna Township Saketh (LM Malleesh)	-