

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		4		4		4			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	4	2	4	2	4	0	0	
	Grand Total	1082	6468	2	5	2	5	2	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Maldakal	33KV	Gadwal	18.36	23.30	04.54	E/L	for Disc Faile & Replacement near Parimalla Stage	Gadwal	No
1	MDK	Gummadidala	GPSS-2	33KV	Patancheru	15.50	17.50	02.00		B/D Due to Conductor Snapped		-

TSSPDCL - LMRC / Corporate office

Date: 05.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Velugupally	Velugupally	11KV	Suryapet	14.30	15.40	01.10		Conductor snapped	-
2		Munagala	Lift	11KV	Huzurnagar	06.00	08.30	02.30		Due to bird fall on 11Kv line	-
3		NG.Bandal	Gandamalla	11KV	Bhongir	11.40	16.20	04.50		11KV Post of Insulteor Failed	-
4		Madgulapally	Kukadam	11KV	Nalgonda	06.00	08.30	02.30		11 KV line Jumper cut	-
1	HYD N	Jubilee Hills	Prasad Eye Institute UG	11KV	Banjarahills	11.28	12.38	01.10	All Indication	Oil leakage from CT at SS	-