

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	6	2	6	2	6	0	0	
	Grand Total	1082	6468	2	7	2	7	2	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Manthathi	33KV	Nagarkurnool	13.45	16.15	02.30	O/L	Tree Fallen on the 33KV Line near Sanduvatla Gate	Manthathi	-
1	NLG	K.M.Pally	Gurrampodu	33KV	Devarakonda	06.40	08.00	01.20		Jumper Cut	Gurrampodu	-

TSSPDCL - LMRC / Corporate office

Date: 06.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Mallepally	11KV	Jadcherla	12.00	16.00	04.00		11KV Jumper Cut near Rajapur	-
1	NLG	Dirshincherla	Dirincherla	11KV	Huzurnagar	04.45	07.15	02.30	EL	11 KV Line Snapped	-
2		Gondiryala	Gondiryala-1	11KV	Huzurnagar	05.20	06.20	01.00	EL	11 KV Line Snapped	-
3		Eduloor	Kurumarthy	11KV	Nalgonda	03.00	08.00	05.00	EL	11KV Jumper Cut	-
4		Kattangur	Dugnally	11KV	Nalgonda	11.00	12.10	01.10	EL	11KV Insulator Failed	-
5		Pamanagundla	Pittampally	11KV	Nalgonda	09.00	11.20	02.20	EL	11KV Insulator Failed	-
1	RR E	Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	14.20	15.00	00.40		Star Wire fallen on 11Kv line at St Jorge School (L Insp Venkateshwarlu)	-