

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1	2	1	2	1	2			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933		4		4		4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	9	1	9	1	9	0	0	
	Grand Total	1082	6468	2	15	2	15	2	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ragunadhpaalem	Nakkagudem	11kv	Huzurnagar	16.30	18.30	02.00	E/L	Jumper cut	-
2		Chityala	Peddakaparthu	11kv	Nalgonda	08.10	10.30	02.00	E/L	11 KV Line Insulator Failed	-
3		Thipparthu	Godavarigudem	11kv	Nalgonda	10.30	14.50	02.00	E/L	11 KV Line Insulator Failed	-
4		Thipparthu	G.Kondaram	11kv	Nalgonda	14.25	16.15	02.00	E/L	11 KV Jumper Cut	-
5		Nalgonda Rural	Kothapally	11kv	Nalgonda	06.30	11.10	02.00	E/L	11 KV Jumper Cut	-
1	MDK	NSF	Mombojipally	11kv	Medak	13.10	15.50	02.40		Break Down 33 KV Jumper Cut	-
2		NSF	Machavaram	11kv	Medak	13.10	15.50	02.40		Break Down 33 KV Jumper Cut	-
3		NSF	Rampur	11kv	Medak	13.10	15.50	02.40		Break Down 33 KV Jumper Cut	-
4		NSF	Chityala	11kv	Medak	13.10	15.50	02.40		Break Down 33 KV Jumper Cut	-
1	RR N	UMCC	Gajularamaram	11kv	Medchal	13.10	13.50	00.40		Bird Fallen on 11KV Line at Chitharamma Temple	-
2		Subhash nagar	Saibaba Nagar	11kv	Medchal	13.40	14.50	01.10		Kite Fallen on 11KV Line at Saibaba Nagar	-
1	RR E	Anand Bagh	Vinayak Nagar	11kv	Sainikpuri	16.45	18.05	01.20		11Kv HG fuse cut at Commutiy Hall near Dav Public School (I.Insp Venu Gopal)	-
2		Aushapur	Edulabad	11kv	Keesara	09.30	10.30	01.00		Insulator fail at Kothagudam aushapur	-
1	HVD S	Miralam	Water Works	11kv	III	16.30	17.38	01.08	EL,OL-Rph	2No. Jumpers cut, HT Lines twisted at Opp. SS & Water Works Filters	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	TTD S	Ch' Baradari	Gazi Banda	11kv	III	17.05	18.42	01.37	EL,OL-Rph	Cable damaged by R&B wing	Arranged B/F on 11KV Khajipura fdr

TSSPDCL - LMRC / Corporate office

Date: 07.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Kollur	33kv	Jadcherla	20.35	21.05	00.30		No visible fault	Kollur	-
1	HYD N	132KV Erragadda	Srinagar Colony	33kv	Erragadda	14.03	14.14	00.11	EL,OL-Rph	33KV Jumper cut at Go Gas Petrol Station, Yousufguda Basthi	Srinagar Colony	Loads transferred onto 132KV Erragadda SS via 33KV Yousufguda feeder