

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1	1	1	1	1	1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	6	3	6	3	6	0	0	
	Grand Total	1082	6468	4	9	4	9	4	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	lthole	33KV	Nagarkurnool	13.00	15.10	02.10	EL	Phase to Phase Near 33KV Kumera SS		-
2		Shadnagar	Stem Core	33KV	Shadnagar	01.35	17.00	15.25	EL	Breaker fault		-
3		Amangal	Polepally	33KV	Shadnagar	13.40	14.45	01.05	OL	R B Phase conductor observed to be fused each other out side SS		-
1	RR S	Shamshabad	Shamshabad	33KV	RJNR	14.40	15.30	00.50	BD	33KV Pin insulator failure at Hamidhulla Villege		-

TSSPDCL - LMRC / Corporate office

Date: 11.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Munagala	Nelamari	11KV	Huzurnagar	06.30	08.10	01.40	EL	11KV Line Snaped	-
2		Marriguda	Marriguda Town	11KV	Devarakonda	14.00	15.05	01.05	E/L	Male & Female	-
3		Angadipeta	P.A./Pally Rural	11KV	Devarakonda	13.05	15.05	02.00	E/L	11 KV Jumper Cut	-
4		Kasarabadha	Express	11KV	Suryapet	10.30	11.30	01.00	E/L	Jumper cut	-
5		Penphad	Anajipuram	11KV	Suryapet	10.50	13.25	02.35	E/L	bird fault	-
6		Madugulapally	Kukkadam	11KV	Nalgonda	07.05	11.50	04.45	E/L	11 KV Insulator Failed and 11 KV jumper Cut	-
1	RR S	Gaganpahad	Minakshi	11KV	RJNR	13.48	15.45	01.57	BD	11KV line twisted at Sathamrai Villege	-
1	RR N	Kandlakoya	KV Reddy Nagar	11KV	Medchal	11.40	12.30	00.50	BD	Tree fallen on the 11KV Line at Gurupreeth company,KV Reddy Nagar	-
1	RR E	Kushaiguda	Kapra	11KV	SKP	13.07	14.00	00.53		11Kv line cut at Saketh Tower (LM Balram)	-