

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933		2		2		2			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	3	16	3	16	3	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Chinnamaroor	Kalwarala	33KV	Wanaparthy	16.10	17.05	00.55	E/L	Insulator Failed Between Weepangandla & Kalwarala	Chinnamaroor	AB Switch open at Weepangandla at 17:05Hrs.
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	14.04	17.05	03.01	E/L	33KV Jumper Cut Near Rayapur (V)	Kethepally, Kopple and Cherkupally	No
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	07.40	08.50	01.10		Bird Fallen on 33KV Line at Kistapur Road		-

TSSPDCL - LMRC / Corporate office

Date: 19.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Alwanpally	11KV	Jadcherla	10.35	13.44	03.09		HT/LT Near Karemulla DTR Side at Gangapur (V)	-
2		Udithyal	Udithyal	11KV	Jadcherla	08.00	09.40	01.40		11 KV Phase To Phase Near Adavibavulu Udithyal(V)	-
3		Karkonda	Kuchur	11KV	Jadcherla	06.50	11.23	04.33		11 KV Wire Cut near Balaswamy Land Revally(V)	-
1	NLG	Sharajipet	Saigudem	11KV	Bhongir	13.30	16.00	02.30	E/L	11KV Pin Insultor Faill in Alair Baypas rood near	-
2		Nuthankal	Chilpakuntla	11KV	Suryapet	14.15	16.55	02.40	E/L	11Kv Insulator flashover	-
3		Kethepally	Korlapahad	11KV	Nalgnda	07.30	12.00	04.30	E/L	HT/LT Line Melt	-
4		SLBC	Kothapally	11KV	Nalgnda	12.30	16.40	04.10	E/L	11 KV Insulator Failed	-
5		Nandipahad	Iyalapuram	11KV	Miryalguda	11.00	16.00	05.00	E/L	Tree Branches fallen on the line near (v)	-
1	MDK	Muddaipet	Pulkal(Agl)	11KV	Jogipet	06.00	10.05	04.05		B/D due to Conductor snapped near Pulkal(V)	-
2		Thadkal	Jamgi	11KV	Jogipet	10.00	12.15	02.15		B/D due to Jumper Cut near Jamgi(V)	-
1	SDPT	Cherial Town	Rollabanda Agl	11KV	Husnabad	06.00	13.00	07.00		BD,Conductor Sanapped	
2		Komuravelly	Komuravelly Agl	11KV	Husnabad	05.05	06.05	01.00		BD,Jumper Cut	
3		Mustyal	Chuchanakota	11KV	Husnabad	06.15	08.10	01.55		BD,Line Fault	-
1	RR N	Medicity	IDA Medicity	11KV	Medchal	05.40	07.00	01.20		Bird Fallen on 11KV Line at Rajabollaram Jutta	-
1	RR E	Nacharam	Bhagya Nagar	11KV	Habsiguda	12.35	13.24	00.49		11KV Line cut near Hyderabad Floor Mill	-
1	HYD C	Golnaka	Moulana Azad Nagar	11KV	Azamabad	10.52	12.10	01.18	EL,OL-Bph	Incoming Cable fault at Matha Temple	-