

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 25.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	GT Giri	Namavaram	11KV	Suryapet	07.30	10.00	02.30	E/L	Jumper cut	-
2		Nuthankal	Yalkapally	11KV	Suryapet	07.00	08.20	01.20	E/L	Insulator flashover at SS-20	-
3		Dirincherla	Chellepally	11KV	Huzurngar	19.30	21.40	02.10	EL	11 KV DISK FAILED	-
4		Garidepally	L B Nagar	11KV	Huzurngar	05.00	08.00	03.00	EL	11 KV LINE SNAPPED	-
5		N B Gudem	Redlakunta	11KV	Huzurngar	18.20	21.55	03.35	EL	11 KV DISK FAILED	-
6		Narkatpally IE	Vanipakala	11KV	Nalgonda	12.12	14.36	02.24	EL	11KV Line Insulator Fialure	-
7		Narkatpally IE	Vatimarathi	11KV	Nalgonda	13.47	14.43	00.56	EL	11 KV Line Jumper Cut	-
8		Thadakamalla	Thadakamalla	11KV	Mirylaguda	10.00	11.30	01.30	EL	Pole damage	-
9		B.Annaram	Kothapeta	11KV	Mirylaguda	11.30	13.00	01.30	EL	Insulator failed	-
1	SDPT	Dubbak	Dubbak	11KV	Siddipet	02.40	06.26	03.46		B/D (Tree Branches Fall on the 11 KV Line)	-

