

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		8		8		8			
3	MDK	107	933		4		4		4			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>18</b>	<b>2</b>	<b>18</b>	<b>2</b>	<b>18</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 26.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gundepuri	Gundepuri	11KV	Suryapet	16.30	17.40	01.10	E/L	Jumper cut	-
2		Repala	Narsimhulagudem	11KV	Huzurnagar	08.30	11.25	02.55	EL	Due tree barnch fall on 11Kv line	-
3		Palakaveedu	Sajjapuram	11KV	Huzurnagar	05.30	08.35	03.05	OL	Due to 11Kv jumper cutted	-
4		Mukundapuram	Kalluru	11KV	Huzurnagar	06.20	08.30	02.10	EL	Due 11Kv Disk Failure	-
5		Thoragal	G.R.Gudem	11KV	Nalgonda	09.15	13.00	03.45	E/L	11 KV Line Jumper Cut Under SS-1	-
6		Teededu	Gajiramthanda	11KV	Devarakonda	12.05	16.00	03.55	E/L	Jumper Cutt	-
7		Marriguda	Marriguda Town	11KV	Devarakonda	12.40	13.10	00.30	E/L	11KV Jumper Cutt	-
8		K.M.Pally	Chennaram	11KV	Devarakonda	13.40	16.20	02.40	E/L	Jumper Cutt	-
1	MDK	Bollaram - I	Sulaxshana-I	11KV	Patancheru	12.00	13.05	01.05		BD due to after petrolling no problem at found	-
2		SOL	Markwell	11KV	Patancheru	12.35	14.05	01.30		BD due to tree fallen on line	-
3		Fathepur	Anthargao	11KV	Jogipet	04.30	06.35	02.05		B/D due to Conductor Snapped near Anthargao(V)	-
4		Peddareddypet	Peddareddypet	11KV	Jogipet	10.30	12.45	02.15		B/D due to Conductor Snapped near Peddareddypet(V)	-
1	SDPT	Komuravelly	Kadaverugu	11KV	Siddipet	13.50	16.10	02.20		Due to Breakdown	
2		Reberthy	Ladnur	11KV	Siddipet	14.50	20.13	05.23		Due to Breakdown	
3		Baswapur	Baswapur	11KV	Siddipet	03.00	09.35	06.35		Due to Breakdown	
1	RR N	Jeedimetla-I	Thriumala	11KV	Jeedimetla	06.30	07.30	01.00	BD	11kv AB Cable problem At Phase-I	-
2		Dp pally	Bowrampet	11KV	Jeedimetla	15.00	17.00	02.00	BD	11kv PIN Insultor Failure Near bowrampet Guest House	-
3		Ravalkole	IDA Ganapathi	11KV	Medchal	12.34	13.56	01.22	BD	Tree Branch fallen on the 11KV Line at Madhava Reddy House Opposite	-

TSSPDCL - LMRC / Corporate office

Date: 26.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Gopalpet	33KV	Wanaparthi	12.10	13.55	01.45	E/L	33KV Conductor Snapped at 132KV Wanaparthi Yard		NO
2		Shadnagar	Rayalseema	33KV	Shadnagar	11.26	13.45	02.19	E/L	Line Petrolling & Tree cutting at Rayalseema Company Supply Stood OK		NO