

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933		3		3		3			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thurumalapur	Dondlapally	11KV	Jadcherla	09.40	13.00	03.20		11KV Jumper Cut near Kuthnepally	No
1	NLG	Jalalpuram	Marrikunta thanda	11KV	Suryapet	9:50	11:40	1:50	E/L	Disc flashover	No
2		Mattampally	Allipuram	11KV	Huzurnagar	13.40	15.20	01.40	EL/OL	Conductor snapped	No
3		Akaram	Akaram	11KV	Nalgonda	12.06	15.00	02.54	E/L	11KV line cut at near by village	No
4		Chinthapally	H.M.Pally	11KV	Devarakonda	01.30	10.50	09.20	E/L	Insulator failed	No
1	MDK	SOL	Markwell	11KV	Sangareddy	1:50	4:10	2:20		Conductor snapped	No
2		Kodur	Minpur	11KV	Jogipet	06.30	09.30	03.00		Conductor snapped	No
3		Raparathi	Raparathi(Agl)	11KV	Jogipet	11.00	13.00	02.00		Jumper cut	No
1	RR E	Mallapur-2	AP Colony	11KV	Habsiguda	6:58	7:45	0:47		11KV Cable failed near Shiva Hotel and 11KV AB switch Opened at Market T/F	No
2		VP Nagar	Ambedkar Nagar	11KV	Sainikpuri	04.00	04.30	00.30		UG cable kit failed at Sai Nagar	No
1	HYD C	Golconda	Mothi Mahal	11KV	Mehdipatnam	02.50	04.45	01.55	EL,OL-Rph	Cable fault at Shajahan Bakery	No

TSSPDCL - LMRC / Corporate office

Date: 30.10.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD S	220KV Ch' Gutta	Santosh Nagar	33KV	Malakpet	13.38	17.00	03.22	All Indi	Rebinded I/C Yph cut Jumper, female contacts, Replaced 6 hole 3No. clamps & 11KV Bus Bar 2No. female contacts at SS	Santosh Nagar	No Change over due to I/C AB Switch Rod broken (at 14:39 Hrs all 11KV feeders arranged B/F)