

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	5	0	5	0	5	0	0	
	Grand Total	1082	6468	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.09.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	24 hrs Feeder	11KV	Jadcherla	07.55	08.50	00.55		Bird died on the 11 KV Line near Shivajinagar Janampet (V)	No
1	NLG	Annaram	Annaam	11KV	Suryapet	6:50	9:30	2:40	E/L	Jumper cut	No
2		Keethavarigudem	Rainigudam	11KV	Huzurnagar	15.49	18.10	02.21	EL	11Kv Disc failed	No
3		Donipamula	Neramta	11KV	Nalgonda	11.24	13.00	01.36	E/L	11KV Insulator failed	No
4		Donipamula	Thimmareddygudem	11KV	Nalgonda	09.00	11.45	02.45	E/L	11KV Jumper cut	No
1	RR N	Thurkapally	Thurkapally	11KV	Medchal	9:05	10:10	1:05		11KV Jumper Cut	No
1	RR E	Singapur	RGK	11KV	Keesara	16:45	19:05	2:20		11KV Pin Insulator failed	No
1	HYD N	N.I.M.S	J.V.R	11KV	Banjara Hills	12.20	13.25	01.05	EL	Cable fault at J.V.R Park	Arranged B/F on 11KV IVRCL for