

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	2	1	2	1	2	1			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	1	3	1	3	1	0	0	
	Grand Total	1082	6468	3	5	3	5	3	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.09.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Achampet	Amrabad	33KV	Nagarkurnool	10.15	14.50	04.35	E/L	LA Blast and LA Removed & By Passed the Jumper at 132KV SS Achampet	Amrabad	No
1	NLG	Ramannapet	Veliminedu	33KV	Nalgonda	6:00	11:00	5:00	E/L	33KV Line Insulator Failure	Veliminedu	No
2		Ramannapet	Chityala	33KV	Nalgonda	16.15	16.45	00.30	E/L	33KV Jumper Cut	Chityala	No

TSSPDCL - LMRC / Corporate office

Date: 05.09.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mushampally	Muthyalammagudem	11KV	Nalgonda	2:00	5:00	3:00	E/L	11KV Insulator failed	No
1	RR S	Gachibowli	Gopanpally	11KV	Gachibowli	15:50	17:40	1:50		Tree fallen on the 11KV Line at Manjeera Diamond.	No
1	RR E	NN Colony	Jammigada	11KV	Habsiguda	5:54	6:24	0:30		11Kv line AB Switch opened at Kushaiguda Drainage (L.Insp Nageshwar Rao)	No
2		Yapral	Kowkooor	11KV	Habsiguda	08.10	08.58	00.48		Bird fallen on 11Kv line at Megadhri Hights Near DNR Function Hall (VAE/OP/Yapral)	No
1	HYD N	Salarjung	City College	11KV	Charminar	19.35	20.55	01.20	All Indication	Tree Branches fallen on lines at Opp.Imlibun Bus stand	No