

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		6		6		6			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	13	0	13	0	13	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	2	3	2	3	2			
2	NLG	144	988	2	3	2	3	2	3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	5	5	5	5	5	0	0	
	Grand Total	1082	6468	5	18	5	18	5	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.09.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanapur	Solipur	33KV	Nagarkurnool	15.31	18.00	02.29		Breaker Problem at 132KV SS	Solipur	Alternate Supply Arranged from Old 11KV Ghanapur at 18:00Hrs.
2		Nagarkurnool	Bijinepally	33KV	Nagarkurnool	02.45	08.40	05.55		Not Found	Bijinepally	Alternate supply Taken to 33KV Lattupally Feeder at 8:40HRs
3		Amarchinta	Atmakur	33KV	Wanaparthi	18.38	18.40	00.02		No Visible fault Supply Stude OK	Atmakur	Alternate Supply Arranged From 33KV Amarchinta at 18:40Hrs.
1	NLG	Ramannapet	Veminedu	33KV	Nalgonda	05.00	08.00	03.00	E/L	33KV Line Insulator Failure	Veminedu	-
2		Ramannapet	Chityala	33KV	Nalgonda	06.15	17.15	01.00	E/L	33KV Jumper Cut	Chityala	-

TSSPDCL - LMRC / Corporate office

Date: 06.09.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Altra Pipes	11KV	Jadcherla	02.05	07.00	04.55		Tree follon the line near	-
2		Balanagar	Mothiganapur	11KV	Jadcherla	10.00	12.58	02.58		Kethireddypally Gate	-
1	NLG	Pamanagundla	Yerrasanigudem	11KV	Nalgonda	12.30	15.30	03.00	E/L	11KV Line Jumper cut	-
2		Eduloor	Kurumarthy	11KV	Nalgonda	14.10	08.00	03.50	E/L	11KV Line Jumper cut	-
3		Mamidala	Aregudem	11KV	Nalgonda	09.30	11.45	02.15	E/L	11KV Insulator failure	-
1	RR N	Aleap	Pragathinagar	11KV	Jeedimetla	04.10	05.10	01.00	BD	Tree branchesh fallon the 11kv line at Aleap	-
2		Aleap	Doctores Colony	11KV	Jeedimetla	04.15	05.40	01.25	BD	11kv line pin Insulater Failed at Akruthi Nilayam at Incoies	-
3		Athiwelly	Somaram	11KV	Medchal	05.25	07.35	02.10	BD	11KV Pin Insulator failed at Rekulabavi	-
4		Uddamarry	Usharpally	11KV	Medchal	05.37	09.10	03.33	BD	11KV Jumper cut at Pothataju temple ,Uddamarry	-
5		Gowdawelly	IDA	11KV	Medchal	08.20	09.50	01.30	BD	11KV Pole damaged by Lorry at Shivaji Statue	-
6		Shameerpet	Alankrita	11KV	Medchal	12.10	15.10	03.00	BD	11KV Jumper cut and replaced at ORR	-
1	RR E	NGRI	Kalyanipuri	11KV	Habsiguda	04.50	06.40	01.50		11KV Post Of Insulator failed and replaced at Sitharam Colony	-
2		Chakripuram	Shilpa Nagar	11KV	Keesara	09.00	09.35	00.35		11KV Jumper cut near Modi Apartment	-
3		P&T Colony	Canara Nagar	11KV	Keesara	05.05	06.30	01.25		Line patrolling but no visible fault	-
4		Peerzathiguda	Peerzathiguda	11KV	Keesara	05.05	06.00	00.55		11KV Pin Insulator failed at Peerzathiguda Municipality Office	-
1	HYD N	H.P.S	Sapthagiri Tower	11KV	Erragadda	07.10	08.20	01.10	EL,OL-Rph	CT, Rph, Oil leakage at SS due to Bird fault	Arranged B/F on 11KV Varun Towers fdr
2		H.A.L	Sowbhagya Nagar	11KV	Bowenpally	16.35	19.30	02.55	EL,OL-Rph	Cable fault	Remaining Loads added on 11KV Giri Nagar fdr
1	HYD S	Petlaburz	Chowk	11KV	Charminar	10.55	12.10	01.15	EL	Cable fault at Chelapura	2No DTRs kept off