

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	1	1	1	1	1	0	0	
	Grand Total	1082	6468	2	2	2	2	2	2	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.09.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Shadnagar	Stem Core	33KV	Shadnagar	11.20	16.15	04.55		R Phase Pin Insulator Damaged at 220KV SS Shadnagar	Stem Core	-
1	HYD C	220KV Shivarampally	Karwan	33KV	Asif Ngr	02.20	02.29	00.09	EL	Cable damaged by GHMC at LOC.No.205	Karwan	Loads transferred onto 132KV Imlibun - Jiyaguda

TSSPDCL - LMRC / Corporate office

Date: 08.09.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kodur	Kommala	11KV	Suryapet	05.00	06.50	01.50	E/L	Jumpercut	-
1	RR E	Kushaiguda	Kamala Nagar	11KV	SKP	18.15	19.05	00.50		Tree branches fallen on 11Kv line at Kamal Kalyan Appartment (AE/AS Rao Nagar)	-