

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	2		2		2				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 09.09.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marikal	Malkapur	11kv	Jadcherla	06.38	08.38	02.00		Tree Fallen on the Line Near Malkapur	-
1	NLG	Kudakuda	MG Nagarhanda	11kv	Suryapeta	11.20	13.20	02.00	E/L	Jumper cut	-
2		Pamanagundla	Yerrasanigudem	11kv	Nalgonda	06.30	09.45	03.15	E/L	Insulator failure	-
3		Palem	Ogodu	11kv	Nalgonda	04.30	07.45	03.15	E/L	11KV Jumper cut	-
1	RR N	Jeedimetla SS-1	Maheshwari	11kv	Jeedimetla	16.10	17.30	01.20	EL/OL	AB Cable failure at Jagadamba, Industrial	-
1	RR E	Vinayak Nagar	Neredmet Dite	11kv	Sainikpuri	15.05	15.25	00.20		11Kv Disk failure at Block 2 Vinayak Nagar (AE/OP)	-

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effectuated	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33kv	Narayanapet	18.55	21.10	02.15	O/L	Due to Phase to Phase Near 132KV SS Maddur	Vepoor	-
2	HYD N	132KV Chilkalguda	Clock Tower	33kv	Secunderabad	23.37	23.47	00.10	EL,OL	R&Yph CT's blast at 33KV Chilkalguda SS	Clock Tower	Loads transferred onto 132KV Gunrock SS via 33KV James Street feeder
1	HYD C	132KV Asif Nagar	Asif Nagar	33kv	Mehdipatnam	14.28	15.51	01.23	OL-Rph	Lightning Arrestor blast on 33KV Bus Section	Asif Nagar	-----