

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		11		11		11			
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	23	0	23	0	23	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1								
2	NLG	144	988		5							
3	MDK	107	933	1	2							
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	0	0	0	0	0	0	
	Grand Total	1082	6468	2	30	0	23	0	23	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.09.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thogarrai	Kuchipudi	11kv	Huzurnagar	19.35	22.30	02.55	EL	Due to 11Kv Jumper cutted	-
2		Kethapally	Gudivada	11kv	Nalgonda	13.00	16.00	03.00	EL	11KV Line Jumper Cut	-
3		Palem	Palem	11kv	Nalgonda	07.30	10.15	02.45	EL	11 KV Insulator Faile	-
4		Avanthipuram	Avanthipuram	11kv	Mirylaguda	05.00	07.30	02.30	EL	Conductor snapped	-
5		Mupparam	Mupparam	11kv	Mirylaguda	08.00	09.20	01.20	EL	Conductor snapped	-
1	MDK	EPIP-I	Chitrakoot	11kv	Sangareddy	10.22	12.15	01.53		B/D due to Conductor snapped at Ozone Systems Co.	-
2		Pati	Pati	11kv	Sangareddy	08.35	10.30	01.55		B/D due to Insulator failed Pati SS	-
1	RR S	IIIT	APHB Colony	11kv	GCB	15.50	16.50	01.00		11KV Breaker Master Relay Problem in Sub-Station.	-
1	RR N	Suraram	Matrix	11kv	Jeedimetla	17.55	18.55	01.00	OL	Crisatorl Company Incomming Said Problem At Phase-IV	-
2		R G K Suraram	R G K	11kv	Jeedimetla	11.25	12.55	01.30	OL	11kv Line Cut Near Pt 85 R G K	-
3		Jeedimetla -III	Pipe line feeder	11kv	Jeedimetla	18.05	19.15	01.10	EL	Due To Rain [Grond petroling No fault}	
4		Jeedimetla -V	Bhagath Sing Nagar	11kv	Jeedimetla	22.05	23.45	01.40	EL/OL	11kv Jumper Snapped Opp Sub Station &11kv Pole Diamage At Pump House Bhagath Sing Nagar	
5		Subhash nagar	Meenakshi	11kv	Medchal	17.35	19.45	02.10		Tree Fallen on the 11KV Line at Meenakshi	
6		UMCC	Mahadevpuram	11kv	Medchal	17.55	18.55	01.00		11KV Pin Insulator Failed at Kailasa Hills	
7		HMT	Manikya Nagar	11kv	Medchal	17.40	18.20	00.40		Tree Fallen on the 11KV Line at Vani Nagar	
8		Kandlakoya	Kandlakoya	11kv	Medchal	18.00	19.25	01.25		Tree Fallen on the 11KV Line at Suthriguda Ring road	-
9		Kandlakoya	KV Reddy Nagar	11kv	Medchal	18.00	19.50	01.50		Tree Fallen on the 11KV Line at KV Reddy Nagar	-
10		Shameerpet	Thumkunta	11kv	Medchal	19.20	20.30	01.10		11KV Pin Insulator Failed at at Thumkunta Village	-
11		GP Pally	GP Pally	11kv	Medchal	17.20	19.50	02.30		Tree Fallen on the 11KV Line at Flipkart Godham	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Vinayak Nagar	Sharda Nagar	11kv	Sainikpuri	20.15	20.35	00.20		11Kv Pin Insulator failed at Chandragiri Colony (AE)	-
2		Kushaiguda	Neredmet	11kv	Sainikpuri	19.20	20.20	01.00		11Kv line AB Switch Opened at Chennai Shopping Mall Due to pin insulator failed at HIG Apartment (AE)	-
3		Yapral	Kowkooor	11kv	Sainikpuri	16.55	17.50	00.55		Tree fallen on 11Kv line at Kowkooor (LM Rajendar)	-
4		Cherelapally-IV	BN Reddy Nagar	11kv	Sainikpuri	19.10	20.00	00.50		11Kv line Patrolling Done But No fault found (FOC Santosh Reddy)	-
5		Cherelapally-IV	BN Reddy Nagar	11kv	Sainikpuri	20.55	21.40	00.45		11Kv line Patrolling Done But No fault found (FOC Santosh Reddy)	-
6		P&T Colony	Medipally	11kv	Keesara	19.40	20.45	01.05		11KV HG Fuse Insulator failed near Rupa apartment at Sai Nagar	-
7		P&T Colony	Canara Nagar	11kv	Keesara	20.05	20.55	00.50		11KV AB Swicth failed and reapiored near Road No.07 at Budda Nagar	-
1	HYD N	Nehru Nagar	West Marredpally	11kv	V	19.17	20.55	01.38	OL-R&Bph	2No. Polymar Insulators flash over Pushpagiri Eye Hospital	
2	HYD S	Malakpet B-Block	Venkatagiri	11kv	VIII	00.55	02.07	01.12	OL-R&Yph	Brass Patti B/o at Venkatagiri Colony	
3		Aliabad	Masrath Function Hall	11kv	III	18.07	19.36	01.29	EL	2No. Top Jumpers cut at Model Colony	
4	HYD C	Amberpet	Golnaka	11kv	II	19.30	21.50	02.20	EL	Cable fault at Vaddera Basti	

TSSPDCL - LMRC / Corporate office

Date: 10.09.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Nanddine	33kv	Gadwal	12.45	15.50	03.05	E/L	33KV Line Phase to Phase	Nanddine	-
1	MDK	Kandhi	SKOL	33kv	Sangareddy	12.20	19.10	06.50		BD due to Insulator failed	SKOL	-