

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		11		11		11			
6	RR(N)	54	550		6		6		6			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		19		19		19			
	Total	606	3055	0	41	0	41	0	41	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5		5		4		1		1 No. 33kv still
2	NLG	144	988	4	10	4	10	4	10			
3	MDK	107	933	4	1	4	1	4	1			
4	SDPT			2		2		2				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	15	11	15	11	14	11	1	0	
	Grand Total	1082	6468	15	52	15	52	14	52	1	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Hanwada	33kv	Mahabubnagar	21.50	00.00	02.10	O/L	Not Rectified	Hanwada	-
2		Maddur	Kothapally	33kv	Narayanpet	20.20	21.50	01.30	E/L	Due to Heavy Wind	Kothapally	-
3		Marikal	Devarkadra	33kv	Narayanpet	19.56	21.05	01.09	O/L	Due to Heavy Wind	Devarkadra	-
4		Gadwal	Alwalpad	33kv	Gadwal	02.47	07.15	04.28	E/L	Jumper Cut at Jampally Canal	Alwalpad	-
5		Shadnagar	Vijayanand	33kv	Shadnagar	14.05	17.40	03.35	E/L & O/L	Binding wire fallen on line at CSK Venture & R & B Phase Jumper Reconnecting at 220KV Shadnagar	Vijayanand	-
1	NLG	Miryalguda	Thripuraram	33kv	Miryalguda	00.12	15.53	15.41	E/L	1. Jumper cut at VK palem canel, 2. Pin insulators failed at Thungapad bandam, Srinivas Nagar	Tripuraram, PD Pally	No
2		Miryalguda	Matoor	33kv	Miryalguda	12.10	16.48	04.38	E/L	Conductor snapped at 220KV SS Miryalguda	Matoor, B.Annaram, Thimmapuram, Regulagadda, Neelaigudem	No
3		Miryalguda	Huzurnagar	33kv	Miryalguda	11.30	16.55	05.25	E/L	Test charged ok fault not identified	Eedulagudem, Nunavath thanda, Kothagudem	33/11KV Eedulagudem SS alternation supply given from 33KV Avanthipuram feeder
4		132KV Wadapally	RWS	33kv	Miryalguda	10.10	12.00	01.50	E/L	Jumper cut near 132 KV wadapally ss	RWS	No
1	MDK	Narayankhed	Kalher	33kv	Jogipet	16.35	17.40	01.05		B/D Due to Jumper cut	Kalher	-
2		Sadasivpet	Kondapur	33kv	Sangareddy	18.05	22.25	04.20		BD Due to kondapur kasaram broken on fallen manjeera feeder at Double circuit point near sspt	Kondapur	-
3		Sadasivpet	Manjeera	33kv	Sangareddy	18.05	22.25	04.20		BD Due to kondapur kasaram broken on fallen manjeera feeder at Double circuit point near sspt	Manjeera	-
4		Pashamailaram	BPL	33kv	Patancheru	19.25	21.30	02.05		BD Due to JUMPER SNAPPED	BPL	-
1	SDPT	Chandlapur	Kamarlapally	33kv	Siddipet	00.00	03.00	00.00		Heavy Gal	Kamarlapally	-
2		Thunki Bollaram	Markook	33kv	Gajwel	00.00	08.04	08.04		Tree fall in line	Markook	-

TSSPDCL - LMRC / Corporate office

Date: 05.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dirsenapally	Alugunuru	11kv	Suryapet	06.00	08.30	02.30	E/L	11Kv Insulator flashover	-
2		Mukundapuram	Mukundapuram	11kv	Huzurnagar	13.45	15.00	01.15	E/L	11Kv Line Snapped	-
3		Gaddipally	Medaram	11kv	Huzurnagar	13.40	15.30	01.50	E/L	11Kv Jumper cut	-
4		Keethavarigudem	Rainigudem	11kv	Huzurnagar	05.00	07.25	02.25	E/L	11Kv Line Snapped	-
5		Amararam	Linagiri	11kv	Huzurnagar	15.30	17.00	01.30	E/L	11Kv Jumper cut	-
6		Madgulapally	Madgulapally (T)	11kv	Nalgonda	02.05	08.30	06.25	E/L	HT/LT Line Melting Near Crasher Mill	-
7		MR.Gudem	Baswapur	11kv	Bhongir	09.55	11.05	01.10	E/L	11kv Line Snapped Near Mutthireddygudem Village	-
8		Manaikunta	Veldevi	11kv	Bhongir	12.00	15.00	03.00	E/L	11kv Jumper Cut Near Veldevi (V)	-
9		Paladugu	Duppelly	11kv	Bhongir	13.30	16.40	03.10	E/L	11kv Line Snapped Near Muddapuram (V) 3 Phase B/d Single Phase OK	-
10		Kapraipally	Kapraipally	11kv	Bhongir	11.50	16.00	04.10	E/L	11kv Jumper Cut at SS-5 Near Kapraipally (V)	-
1	MDK	Gaddapotharam - I	Vishnu	11kv	Patancheru	01.00	07.23	06.23		BD due to Conductor snapped	-
1	RR S	MD Pally	MD Pally (V)	11kv	RJNR	19.30	20.10	00.40	B/D	LAB Switch opened at MD Pally Village	-
2		Madinaguda	Allwyn Colony	11kv	Gachibowli	07.05	08.22	01.17		Tree fallen on 11KV line at Mythri apartment	-
3		IJM	New 6th Phase	11kv	Gachibowli	18.14	19.25	01.11		Due to Rain & Wind	-
4		Mathrusri Nagar	Vishwambara	11kv	Gachibowli	18.10	19.50	01.40		Tree fallen on 11KV line at Chaitanya college, opposite	-
5		Mathrusri Nagar	Srila	11kv	Gachibowli	18.10	19.50	01.40		Tree fallen on 11KV line at Plot no-35/A	-
6		KPHB	6th Phase	11kv	Gachibowli	18.25	21.04	02.39		Coconut tree fallen on 11KV line at HIG-379	-
7		KPHB	KPHB	11kv	Kondapur	18.25	20.50	02.25		Polymer insulator failed at MIG-600	-
8		KPHB	Dharmareddy	11kv	Kondapur	19.58	21.25	01.27		Polymer insulator failed at Ramalayam temple	-
9		Lodha	5th Phase	11kv	Kondapur	19.20	20.30	01.10		Cover fallen on 11KV line at HIG-7	-
10		Ayyappa Society	Hyundai	11kv	Kondapur	19.25	20.35	01.10		Flexy fallen on 11KV line at Petrolbunk	-
11		Ayyappa Society	Parwath Nagar	11kv	Kondapur	19.30	20.45	01.15		11kv Pin insulator failed at Parwath Nagar	-
1	RR N	Chinthal	Surya Nagar	11kv	Medchal	19.25	20.15	00.50		11KV Pin Insulator failed at Vinayaka Temple Surya nagar	-
2		Ravalkole	IDA Ganapathi	11kv	Medchal	00.00	01.42	01.42		11KV Line touched to 33KV Tower at Rajabollaram thanda	-
3		UMCC	RM Nagar	11kv	Medchal	19.20	22.05	02.45		11KV Pin Insulator failed at chandragirinagar	-
4		JNTU	Nandamuri Nagar	11kv	Kukatpally	18.07	20.30	02.23		Tree Branches Fall on the 11kv line at Pool mun Company ,Hydernagar {Due to rain }	-
5		Mayurinagar	Gokarajurangeraju	11kv	Kukatpally	18.48	20.20	01.32		Cloth Fallon the 11kv line at RL City Back side {Due to Rain }	-
6		Prashanthi nagar	Mythri nagar	11kv	Kukatpally	18.20	20.30	02.10		11kv line jumper Re-binding at Metro Back side {Due to Rain }	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Sai Nagar	Maruthi Nagar	11kv	Habsiguda	20.27	21.50	01.23		Line patrolling but no visible fault	-
2		Uppal Kalsa	Shanthi Nagar	11kv	Habsiguda	20.55	22.15	01.20		Tree fallen on 11kv line at Shanthi Nagar Bottle Company	-
3		Nacharam	Nile	11kv	Habsiguda	20.35	21.48	01.13		11KV Pin Insulator failed at Nile Company	-
4		P&T Colony	NIN	11kv	Keesara	17.05	19.35	02.30		Lizard fallen on 11KV NIN Colony feeder breaker in SS Yard	-
5		Singapur	RGK	11kv	Keesara	20.45	23.45	03.00		11KV Jumper cut & 11KV Pin Insulator failed at Annojiguda Flyover & Tree Fallen on 11Kv Line RGK Main Road	-
1	HYD N	Pragatools	R.R.Nagar	11kv	VI	00.02	01.50	01.48	EL,OL-Rph	Conductor snapped & Insulator flash over in Jangal Bit	----
2		Macha Bollaram	Sai Reddy Nagar	11kv	C-VI	00.15	01.55	01.40	EL,OL-Rph	No Visible Fault	----
3		Lodha	I.E.	11kv	IV	18.12	21.25	03.13	OL-Rph	HT Jumper cut at Industrial Area (1No. DTR kept off)	----
4		I.D.P.L	Bala Nagar	11kv	VI	18.20	19.35	01.15	EL	Tree branches fallen on lines at Bala Nagar	----
5		Srinagar Colony	Udyog Nagar	11kv	X	18.21	19.55	01.34	EL,OL-Bph	No Visible Fault	----
6		H.P.S.	Varun Towers	11kv	IV	18.23	19.37	01.14	EL,OL-R&Bph	Tree branches fallen on lines at Varun Towers	----
7		Prashanth Nagar	Shakthipuram	11kv	VI	18.25	21.10	02.45	EL,OL	Faulty AB Switch at Shakthipuram	----
8		E.S.I	Bapu Nagar	11kv	IV	18.25	20.21	01.56	EL,OL-Bph	Tree branches fallen on lines at B.K Guda	----
9		H.A.L	Samrat	11kv	VI	18.25	19.33	01.08	EL	No Visible Fault	----
10		I.D.P.L	Wonder Plast	11kv	VI	18.25	20.40	02.15	EL	HT Line snapped at Patney Systems	----
11		H.M.T.	Sri Sai Colony	11kv	VI	18.40	22.20	03.40	EL	No Visible Fault	----
12		Bowenpally	Pipe Line Road	11kv	VI	18.50	20.30	01.40	EL,OL-Bph	Tree branches fallen on lines at Pipe Line Road	----
13		Bowenpally	B.B.R Hospital	11kv	VI	18.50	20.00	01.10	EL,OL-R&Bph	Tree branches fallen on lines at Narsapur X-Roads	----
14		Bowenpally	Gowtham Nagar	11kv	VI	18.50	19.50	01.00	EL,OL-Y&Bph	Tree branches fallen on lines at Timber Depot	----
15		Bowenpally	I.A.F.	11kv	VI	18.50	21.35	02.45	EL,OL-Rph	Due to rain	Arranged B/F on 11KV IAL feeder
16		Ravindra Society	Sai Nagar	11kv	X	19.42	20.55	01.13	OL-R&Yph	Tree branches fallen on lines at Ayyappa Society	----
1	Hyd C	Industrial Area	RTC X Road	11kv	II	20.20	21.30	01.10	EL,OL-R&Bph	Tree branches fallen on lines at Risalagadda	----
2		Jawahar Nagar	Ashok Nagar	11kv	I	18.30	19.45	01.15	EL,OL-Bph	Tree branches fallen on lines at Jawahar Nagar	----
1	Hyd S	Malakpet	Komatiwadi	11kv	VIII	20.30	22.15	01.45	EL,OL-Yph	Brass Patti burntout at Ali Nagar	----