

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		18		18		18			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		16		16		16			
	Total	606	3055	0	38	0	38	0	38	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	7		7		7				
2	NLG	144	988	5	16	5	16	5	16			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	12	16	12	16	12	16	0	0	
	Grand Total	1082	6468	12	54	12	54	12	54	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Jadcherla	33KV	Mahabubnagar	18.20	21.05	02.45	E/L & O/L	Disc insulator replacement at SVS Dental Hospital	Jadcherla	No
2		Kosgi	Mirzapur	33KV	Mahabubnagar	17.20	17.40	00.20	O/L	Due to Heavy Gale & Wind	Mirzapur	Alternate Supply Arranged at 33KV Kosgi Feeder at 17:40Hrs
3		Midjil	Velugomula	33KV	Jadcherla	18.40	21.05	02.25	E/L	33KV Jumper cut Ediganpally	Velugomula	No
4		Midjil	Madaram	33KV	Jadcherla	19:15	21:05	1:50	E/L	33KV Jumepr cut at Boinpally	Madaram	No
5		Marikal	Kondapur	33KV	Narayanapet	18:40	21:00	2:20	O/L	Insulator damaged at Kistapur Kondapur	Kondapur	Alternate supply arranged from at 33KV Koilkonda Water Grid feeder at 21:00Hrs
6		Marikal	Devarkadra	33KV	Narayanapet	18:15	20:45	2:30	O/L	Insulator Damaged at Pellair	Devarkadra	No
7		Alwal	Padkal	33KV	Shadnagar	18.18	18.48	00.30	E/L	Due to Heavy Wind and Breakdown AB switch open at Padi Gadda line supply stood OK	Padkal	No
1	NLG	Dirincherla	Garedepally	33KV	Huzurnagar	11:20	15:10	3:50	EL	Due to heavy rain	Garedepally	No
2		Dirincherla	Keethavarigudem	33KV	Huzurnagar	11.26	14.20	03.06	EL	Due to heavy rain	Keethavarigudem	No
3		Munagala	Akupamula	33KV	Huzurnagar	10.30	11.30	01.00	EL/OL	Pin insulator failed	Akupamula	No
4		Kolanpaka	Y.Gutta	33KV	Bhongiri	15.45	16.35	00.50	EL/OL	33KV Jumper cut	Y.Gutta	No
5		Kolanpaka	Raghunathpur	33KV	Bhongiri	15:30	16:35	1:35	EL	Tree branches fallen near Kolanpaka Vaagu	Raghunathpur	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ramachandrapuram	Ramachandrapuram	11KV	Suryapeta	13:15	15:00	1:45	E/L	Insulator flashover	No
2		Koppole(K)	Bhemaram	11KV	Nalgonda	06.00	07.45	01.45	E/L	11KV Line Jumper Cut	No
3		Kattangur	Mallaram	11KV	Nalgonda	08.00	10.20	02.20	E/L	11KV Line Insulator failure	No
4		Mukundapuram	Dacharam	11KV	Huzurnagar	04.00	06.00	02.00	E/L	11 KV Line snapped	No
5		G.Malkapuram	Chinthalapalem	11KV	Huzurnagar	14.00	16.00	02.00	E/L	11 KV Line snapped	No
6		Ananthagiri	Mogalikota	11KV	Huzurnagar	05.30	07.00	01.30	E/L	11 KV Line snapped	No
7		MT.Pally	Dharmaram	11KV	Bhongir	01.00	07.50	07.50	E/L	Due to Heavy Gail & Rain, No visible fault	No
8		NG.Bandal	Gandamalla	11KV	Bhongir	18.00	07.00	13.00	E/L	11 KV Pin insulator failed near Sub station 8 th Pole. Heavy Gail & Rain	No
9		Kolanpaka	Raghvapur	11KV	Bhongir	13.40	17.30	03.50	E/L	11kv Line Snapped at SS-2	No
10		Kolanpaka	Somaram	11KV	Bhongir	13.45	16.30	02.45	E/L	SS-6 11kv Line Snapped Kolanpaka Village	No
11		Alair 2	Alair Agl	11KV	Bhongir	14.20	17.40	03.20	E/L	11kv Line Snapped at Alair Village	No
12		D.Nagaram	D.Nagaram Agl	11KV	Choutuppal	10.40	12.40	02.00	E/L	11kv Insulator failed In Allapuram Village Due to Heavy Gale	No
13		Varkatpally	Gokaram	11KV	Choutuppal	15.40	17.30	01.50	E/L	HT/LT near Gokaram Village	No
14		Koyyalagudem	Dhothigudem Indl	11KV	Choutuppal	10.37	14.20	03.43	E/L	11KV Insulator failed & Bird fallen at line near Koyyalagudem Village	No
15		Pulicherla	Utlapally	11KV	Miryalaguda	10.12	11.24	01.12	E/L	Pin binding replaced	No
16		Settipalem	Settipalem-I	11KV	Miryalaguda	12:15	13:40	1:25	E/L	Jumper cut	No
1	RR N	G vikas	Vikas	11KV	Kukatpally	18:10	19:30	1:20	EL/OL	11kv Limb problem In sub station	No
2		Jeedimetla-III	USP organic	11KV	Jeedimetla	16.00	19.25	03.25	EL	11kv AB cable failure At Dims pharama company	No
3		Jeedimetla-III	Andhrapolyamer	11KV	Jeedimetla	16.05	17.45	01.40	EL	Due To Heavy Rain	No
4		Jeedimetla-III	Back let Hylem	11KV	Jeedimetla	13.15	14.25	01.10	EL	11kv AB cable failure At Saastik Cable Company	No
5		Chinthal	Dwaraka Nagar	11KV	Medchal	13:00	13:40	0:40	BD	11KV UG Cable Failed at Dwaraka Nagar	Back feeding arranged from 11KV Ganesh Nagar & 11KV Manikya Nagar
6		HMT	Manikya Nagar	11KV	Medchal	16:20	18:20	2:00	BD	11KV Jumper Cut in SS and Tree Fallen on 11KV Line at Vani Nagar	No
7		Subhash Nagar	Bank Colony	11KV	Medchal	16:23	18:10	1:47	BD	Tree Fallen on 11KV Line at SR DG School	No
8		Bachupally	SMS	11KV	Kukatpally	8:45	9:45	1:00	BD	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
9		Bachupally	Sainagar	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
10		Bachupally	Mallampet	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
11		Bachupally	AC Tyres	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
12		Bachupally	Nizampet	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
13		Bachupally	Mytas	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
14		Bachupally	Maa Villash	11KV	Kukatpally	8:45	9:45	1:00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
15		Bachupally	Pranitha	11KV	Kukatpally	08.45	09.45	01.00	EL/OL	Lorry dash to the 11kv poles 11 nos Poles damaged Near sub Station	No
16		Dp pally	I D A Gagillapur Cable	11KV	Jeedimetla	11.16	14.16	03.00	EL	11kv UG cable failure At Ring Road	No
17		Dp pally	Bowrampet	11KV	Jeedimetla	18.30	21.30	03.00	EL/OL	Laxama Reddy T/F HT Side Insultor Failure at RingRoad	No
18		R G K Suraram	Krushy colony	11KV	Jeedimetla	16:03	17:03	1:00	OL	Due To Heavy Rain	No

1	RR E	NGRI	Scientist colony	11KV	Habsiguda	11:28	13:15	1:47		Post of insulator failed at Deccan furniture main road HBG	No
2		Moula-Ali	Malkajgiri	11KV	Sainikpuri	15.31	17.46	02.15		11Kv Insulator on 33Kv Tower failed at ZTS 'X' Road	No
3		Singapur	Annojiguda	11KV	Keesara	15.10	17.00	01.50		HT/LT line jumper cut at LIG road	No
4		Narapally	P.Singaram	11KV	Keesara	00.10	01.15	01.05		Disc failed at Balaji nagar	No
1	HYD N	Jubilee Hills	I.O.A	11KV	Jubilee Hills	06.30	07.38	01.08	All Indication	Twisted Lines at Road No.83	Arranged B/F on 11KV Daspalla feeder
2		Prashanth Nagar	Shakthipuram	11KV	Bowenpally	15:15	17:55	2:40	EL	Tree branches on lines & Pin Insulator flash over at Shankthipuram	No
3		I.D.P.L	Bala Nagar	11KV	Bowenpally	16:20	17:35	1:15	EL,OL-Rph	Jumper Cut & Insulator flash over at Prakash Paints	No
4		H.A.L	Sowbhagya Nagar	11KV	Bowenpally	16:06	18:10	2:04	EL	No Visible Fault (Due to Rain)	No
5		Prashanth Nagar	Andhra Jyothi	11KV	Bowenpally	16:45	17:55	1:10	EL	O/G Jumper cut at SS	No
6		H.M.T	Sri Sai Colony	11KV	Bowenpally	16.20	18.50	02.30	EL,OL	Tree branches on lines	No
1	HYD S	Falaknuma	Fathima Nagar	11KV	Charminar	15.55	17.30	01.35	EL	No Visible Fault (Due to Rain)	No
2		Devibagh	Kamela	11KV	Charminar	16:00	18:17	2:17	EL	sparking AB Switch at Maharaja Functional Hall	No
3		Santosh Nagar	Riyasath Nagar	11KV	Charminar	16:40	18:30	1:50	EL	HT lines twisted at Anwar Hotel	No
1	HYD C	Golconda	Aditya Nagar Cable	11KV	Mehdipatnam	15.45	17.14	01.29	EL	No Visible Fault (Due to Rain)	No
2		Golconda	Brindhavan Colony	11KV	Mehdipatnam	15.45	17.10	01.25	EL,OL	No Visible Fault (Due to Rain)	No
3		Golconda	Aditya Nagar OH	11KV	Mehdipatnam	15.52	17.13	01.21	EL	No Visible Fault (Due to Rain)	No
4		Golconda	Shaikpet W.W	11KV	Mehdipatnam	15:54	17:20	1:26	EL,OL-Bph	No Visible Fault (Due to Rain)	No
5		Asif Nagar	Padmanabaha Nagar	11KV	Mehdipatnam	15:52	17:25	1:33	EL	Tree branches on lines at P&T Colony	No
6		Golconda	Darga Cable	11KV	Mehdipatnam	16:45	18:10	1:25	EL	Cable End Kit fault at Dowlath Plaza	No
7		Golconda	O.U Colony	11KV	Mehdipatnam	17.55	19.17	01.22	EL	Cable fault	18:40 Hrs Partial loads added on 11KV Darga OH fdr & Remaining Loads added on 11KV Shaikpet W.W fdr