

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		16		16		16			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	18	1	18	1	18	0	0	
	Grand Total	1082	6468	1	21	1	21	1	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.04.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Surya Jyothi (MYK)	33KV	Shadnagar	16.30	18.15	01.45	E/L & O/L	for LA Failure at Roto Pack Industrial	Surya Jyothi (MYK)	-

TSSPDCL - LMRC / Corporate office

Date: 07.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Kethireddypally	11KV	Jadcherla	08.12	11.25	03.13		11Kv Insulator Failure And 11 Kv Wire Cut Near Kethireddy pally (Vi).	-
1	NLG	Singarajpally	Bramanapally	11KV	Devarakonda	07.00	10.30	03.30	EL	Conductor snapped	-
2		Singarajpally	Thawakalapoor	11KV	Devarakonda	06.00	08.00	02.00	EL	Conductor snapped	-
3		Singarajpally	Veeraboina pally	11KV	Devarakonda	08.30	12.00	03.30	EL	Disc failed	-
4		Laxmi Devi Gudem	Laxmi Devi Gudem	11KV	Miryalaguda	09.55	12.10	02.15	EL	Conductor snapped	-
5		Indugula	Malparajudam	11KV	Nalgonda	14.58	16.50	01.52	EL	11KV Line Jumper Cut	-
6		Turkapally	Kachalapuram	11KV	Nalgonda	13.55	16.40	02.45	EL	Tree fallen on line	-
7		Pamangundla	Industrial	11KV	Nalgonda	05.00	07.40	02.40	EL	Tree fallen on line	-
8		Dirsenapally	Chinnanemila	11KV	Suryapet	03.20	06.00	02.40	EL	Insulator flashover	-
9		Phanigiri	Phanigiri Agl	11KV	Suryapet	08.30	12.00	03.30	EL	Disc flashover	-
10		Dirincherla	Dirincherla	11KV	Huzurnagar	05.00	06.30	01.30	EL	11 KV INSLATER FAILED	-
11		BNL THANDA	Pathanda	11KV	Huzurnagar	05.30	07.30	02.00	EL	11 KV LINE SNAPPED	-
12		Pedaveedu	Krishna thanda	11KV	Huzurnagar	12.00	14.00	02.00	EL	11 KV JUMPER CUT	-
13		Mattapally	Mattapally town	11KV	Huzurnagar	02.30	04.00	01.30	EL	11 KV LINE SNAPPED	-
14		Alair	Chinna Kandukur	11KV	Bhongir	11.30	12.30	01.00	EL	11 kv Line Snapped SS- 1 pole Near Sub Station	-
15		Juloor	Peddagudem	11KV	Choutuppal	06.30	09.02	02.32	EL	11 KV Insulator Fail & 11 kv Line Snapped Near Peddagudem village	-
16		Juloor	Kapraipally	11KV	Choutuppal	09.58	11.34	01.36	EL	11 KV Insulator Fail & 11 kv Line Snapped Near Juloor village	-
1	MDK	Anrich Bollaram	Town-II	11KV	Patancheru	11.55	13.15	01.20		B/D Due to Conductor Snapped	-
1	RR E	Nacharam	Muktha metal	11KV	Habsiguda	00.51	01.45	00.54		Tree branches fallen on 11kv line at Paint company	-
2		Kushaiguda	Kapra	11KV	Sainikpuri	17.55	18.45	00.50		Big Tree fallen on Remove with JCB 11Kv line at Ganesh Temple Kapra (AE/SKP)	-
1	HYD C	Bathkammakunta	Saibaba Temple	11KV	II	09.50	11.20	01.30	EL	Coconut branches fallen on lines at Plot No.927 (Partial fdr charged at 10:25 Hrs)	-