

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		44		44		44			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	45	2	45	2	45	0	0	
	Grand Total	1082	6468	2	53	2	53	2	53	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.04.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	leeza	Gattu	33KV	Gadwal	18.55	19.00	00.05	E/L&O/L	Due to Heavy wind	Gattu	Alternate Supply Arranged From 33KV Mitta Doddy at 19:00Hrs
2		Kothur	Ennar Steel	33KV	Shadnagar	21.30	23.56	02.26	E/L	Disc Insulator Failed Near Bawarchi Hotel	Ennar Steel	-

TSSPDCL - LMRC / Corporate office

Date: 21.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Sri ram thanda	11KV	Suryapet	09.00	11.00	02.00	E/L	11Kv Insulator failed	-
2		Dirincherla	Narsaigudem	11KV	Huzurnagar	05.00	07.30	02.30	E/L	11Kv Jumper Cut	-
3		Dirincherla	Yallapuram	11KV	Huzurnagar	05.00	08.30	03.30	E/L	AB Switch Jumper Cut	-
4		Palakeedu	Palakeedu	11KV	Huzurnagar	06.00	09.30	03.30	E/L	11Kv Line Snapped	-
5		Palakeedu	Sajjapuram	11KV	Huzurnagar	05.00	08.00	03.00	E/L	11Kv Jumper Cut	-
6		Akaram	Vaddipamula	11KV	Nalgonda	06.00	15.00	09.00	E/L	11KV Line Cut And Big tree Fail On The Line.	-
7		Akaram	Shanthinagar	11KV	Nalgonda	06.00	14.00	08;00	E/L	11KV Line Cutting And Tree Branches On The Line	-
8		Edulur	Munukuntla	11KV	Nalgonda	05.30	08.30	03.00	E/L	HT/LT Line Cutting	-
9		Katangur	Mallaram	11KV	Nalgonda	06.00	14.00	08.00	E/L	Tree Branches On The Line	-
10		Katangur	Dugunavelly	11KV	Nalgonda	06.00	10.40	04.40	E/L	11KV Line Insulator Failur	-
11		Katangur	Bollepally	11KV	Nalgonda	06.00	11.00	11.00	E/L	11KV Line Jumper Cutting	-
12		Kesharajupally	Kesharajupally	11KV	Nalgonda	08.00	12.00	04.00	E/L	11KV Line Insulator Failur And Tree fail On The Line	-
13		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	06.30	12.30	06.00	E/L	HT/LT Line Cutting	-
14		Pullemla	Pullemla	11KV	Nalgonda	05.40	09.00	03.20	E/L	SS-2 11KV Line Insulator failur	-
15		P.D.Pally	P.D.Pally	11KV	Nalgonda	14.00	16.00	02.00	E/L	11KV Jumper Cutting	-
16		P.D.Pally	Kondaram	11KV	Nalgonda	14.00	16.30	02.30	E/L	11KV Disc Failur	-
17		Shaligouraram	Gurajala	11KV	Nalgonda	07.30	10.00	02.30	E/L	11KV Line Cutting	-
18		SLBC	darveshipuram	11KV	Nalgonda	06.00	12.30	06.30	E/L	11KV Line Insulator Failur	-
19		Velugupally	Velugupally	11KV	Nalgonda	04.00	14.00	14.00	E/L	HT/LT Line Cutting	-
20		Velugupally	Ithavarigudem	11KV	Nalgonda	06.30	09.40	03.10	E/L	Tree Branches On The Line	-
21		Velugupally	A.R.Gudem	11KV	Nalgonda	06.30	08.30	02.00	E/L	11KV Line Jumper Cutting	-
22		Agamothkur	Chirumarthi	11KV	Miryalguda	10.24	10.40	00.16	E/L	11KV jumper cut	-
23		Seethya Thanda	Vemulapally	11KV	Miryalguda	12.35	12.50	00.15	E/L	Fuse blown	-
24		Rajavaram	Tirumalagiri	11KV	Miryalguda	04.51	06.40	01.49	E/L	Heavy gale/wind	-
25		Rajavaram	J.C Thanda	11KV	Miryalguda	04.51	07.36	02.45	E/L	11KV jumper cut	-
26		Neelaigudem	Neelaigudem	11KV	Miryalguda	00.00	06.28	06.28	E/L	Conductor snapped	-
27		Laxmi Devi gudem	Keshavapuram	11KV	Miryalguda	09.00	12.00	03.00	E/L	11KV jumper cut	-
28		A.D.Pally	Ulsaipalem	11KV	Miryalguda	08.30	11.40	03.10	E/L	11KV jumper cut	-
29		Seetya Thanda	T.P.C.L-1	11KV	Miryalguda	16.18	17.24	01.06	E/L	L.C/fire near T.F	-
30		Shettipalem	Vemulapally	11KV	Miryalguda	02.30	06.00	03.30	E/L	Jumper Cut	-
31		Buggabaigudem	V.pally	11KV	Miryalguda	13.15	13.30	00.15	E/L	Jumper Cut	-
32		P.D.Pally	Gajala puram	11KV	Miryalguda	19.32	08.18	12.46	E/L	Jumper Cut	-
33		Kamareddy gudem	Kamareddy gudem	11KV	Miryalguda	08.01	08.06	00.05	E/L	Jumper cut	-
34		M.R.Gudem	Gangasanipally	11KV	Bhongir	09.00	12.00	03.00	EL/OL	HT/HT Kunti muthaiah Well Near Muthireddy gudem Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
35		NG.Bandal	Veerareddypally	11KV	Bhongir	04.00	09.15	05.15	EL/OL	Phase to Phase at Kettekunta Village.3 Phase B/d Single Phase OK	-
36		Nemaragommula	Nemaragommula	11KV	Bhongir	17.12	19.40	02.28	EL/OL	2 no's LT pole Dammaged in Nemaragommula Village.	-
37		Maryala	Chowderpally	11KV	Bhongir	17.30	19.25	01.55	EL/OL	3 no's LT Poles Dammaged Chowderpally Village	-
38		Alair	Ikkurthy	11KV	Bhongir	03.30	08.15	04.45	EL	11 kv Line Snapped Near Bahudurpet Village. 3 Phase B/d Single Phase OK	-
39		Motakodur	Motakodur	11KV	Bhongir	08.30	10.00	01.30	EL/OL	3 No's. 11 KV Insulators Failed Pirla Well, Near Motakondur Village. 25 DTR's OFF.3 Phase B/d Single Phase OK	-
40		Motakodur	Motakodur Indl	11KV	Bhongir	12.40	13.20	00.40	EL	11 kv Insulator Failed at Mohan reddy well Near Giriboina gudem	-
41		Alair 2	Alair Agl	11KV	Bhongir	04.30	08.15	03.45	EL	11 kv Line Snapped Near Bahudurpet Village. 3 Phase B/d Single Phase OK	-
42		Pamukunta	Jala	11KV	Bhongir	09.15	14.15	05.00	EL	1 No LT Pole Dammaged ,Kotha Jala Poultry Farm Jumper Open, 15 DTR's OFF	-
43		Manaikunta	Veldevi	11KV	Bhongir	20.35	08.56	12.22	EL/OL	1 No. 11 kv pole Dammaged & jumper open Near Veldevi village out side 5 DTR's OFF.Hevay Gale & wind	-
44		Velmajala	Seetharampuram	11KV	Bhongir	05.30	08.00	02.30	EL/OL	Phase to Phase at Chippalakunta Near Seetharampur Village.3 Phase B/d Single Phase OK	-
1	MDK	Dunidigal	Bonthapally	11KV	Patancheruvu	01.50	06.03	04.13		Conductor snapped	-
1	RR S	Nanakramguda	Manjeera	11KV	GCB	07.36	08.36	01.00	BD	Bird fallen on the 11kv line at Muppa Apartments, Thanda	-
1		Subhash Nagar	Pragha Tools	11KV	Medchal	06.35	07.56	01.21		HT/LT Line melted at BHEL Road	-
2		Bommarajpet	Karkamma	11KV	Medchal	14.47	17.00	02.13		11KV Pin Insulator failed at Bommara pet Village	-
3		Kolthur	Mallannakatta	11KV	Medchal	15.20	18.30	03.10		100KVA T/F failed at Anatharam Road	-
4		Keshavaram	Uddamarry	11KV	Medchal	15.20	16.50	01.30		11KV Pin Insulator failed at Babaguda Village	-
5		Bowrampet	Bowrampet Village	11KV	Jeedimetla	16.20	18.00	01.40	EL/OL	11kv Line conductor snaped a Okradge school, Bowrampet Village	-
1	HYD S	Devi Bagh	Zoo Quarters	11KV	III	05.26	06.28	01.02	OL	Cable fault	Arranged B/F on 11KV Kishan Bagh AB Cable fdr
1	HYD C	Lumbini Park	Lumbini Park	11KV	I	19.14	21.40	02.26	All Indication	PTR fuse burnt out in Lumbini Park	-