

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	4	23	4	23	4	23			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	24	4	24	4	24	0	0	
	Grand Total	1082	6468	4	26	4	26	4	26	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.04.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Shantinagar	Akupamula	33KV	Huzurnagar	0:00	9:40	9:40	EL	Due 33Kv insulator failure	Akupamula	No
2		Mattampally	B.N.L.Thanda	33KV	Huzurnagar	08.00	11.00	03.00	EL/OL	Due 33Kv jumper open in the SS	B.N.L.Thanda	No
3		shaligouraram	Cherukupally	33KV	Nalgonda	07.30	11.30	04.00	EL	Tree branches fallen on the line	Cherukupally	No
4		K.M.Pally	Angadipeta	33KV	Devarakonda	20.00	21.30	01.30	EL	HT/LT	Angadipeta	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nuthankal	Somlathanda	11KV	Suryapet	9:30	12:10	2:40	E/L	Line cut near Chilpakuntla Village	No
2		Munagala	Lift	11KV	Huzurnagar	12.45	16.10	03.25	EL	Due to 11Kv line snapped	No
3		Munagala	Kokkireni-II	11KV	Huzurnagar	12.15	16.10	03.55	EL	Due to 11Kv jumper cutted	No
4		Nadigudem	Nadigudem	11KV	Huzurnagar	07.00	10.30	03.30	EL	Due to 11Kv line twisted	No
5		Thogarrai	Ganapavaram	11KV	Huzurnagar	18.30	21.28	02.58	EL	Due to Tree branch fall on 11kv line	No
6		Kandibanda	Kandibanda	11KV	Huzurnagar	18.35	22.04	03.29	EL	Due to 11Kv line snapped	No
7		Kistapuram	Thammaram	11KV	Huzurnagar	20.30	23.50	03.20	EL	Due to 11Kv jumper cutted	No
8		Kistapuram	Kistapuram	11KV	Huzurnagar	19.30	21.50	02.20	EL	Due to 11Kv Insulator failure	No
9		Pamangundla	Pittampally	11KV	Nalgonda	05.40	08.20	02.40	EL	Jumper Cut	No
10		Pamangundla	Yerrasanigudem	11KV	Nalgonda	06.00	09.00	03.00	EL	Insulator failed	No
11		Rajupeta	Jangadigudem	11KV	Nalgonda	12.30	06.30	06.00	EL	Jumper Cut	No
12		Nakrekal	Chandempally AGL	11KV	Nalgonda	18.00	09.30	15.30	EL	Tree branches fallen on the line	No
13		Nakrekal	Kadaparthi AGL	11KV	Nalgonda	18.00	07.00	13.00	EL	Insulator failed	No
14		Nakrekal	Chandupatla	11KV	Nalgonda	18.00	06.00	12.00	EL	Tree branches on the line	No
15		Katangur	Mallaram	11KV	Nalgonda	06.00	09.30	03.30	EL	Disk failure	No
16		Madgulapally	Indugula	11KV	Nalgonda	12.17	14.05	01.48	EL	Insulator failed	No
17		Madgulapally	Kalimera	11KV	Nalgonda	06.00	10.00	04.00	EL	HT/LT line milting	No
18		Padamtipally	Iddampally	11KV	Devarakonda	08.00	10.30	02.30	O/L	HT/HT	No
19		Tatioki	Gollapally	11KV	Devarakonda	06.00	08.30	02.30	E/L	Jumper cutt	No
20		Pendlipakala	Pendlipakala	11KV	Devarakonda	13.58	16.40	02.42	E/L	11KV Line Touched The V X Armas	No
21		Singarajupally	Veeraboinapally	11KV	Devarakonda	09.00	11.00	02.00	E/L	11 kV Disc Failed	No
22		Ghanapuram	Kodandapuram	11KV	Devarakonda	09.30	14.00	04.30	E/L	11KV Line Cutt	No
23		Pittalagudam	Vattikod	11KV	Devarakonda	14:00	15:00	1:00	E/L	Movement Fault	No
1	MDK	Bollaram - I	Soubhagya	11KV	Patancheru	18:52	21:40	2:48		Due to Underline cable failed	No
1	RR E	Sai Nagar	RNS Colony	11KV	Habsiguda	9:45	11:05	1:20		No visible fault	No
2		Moulali	Malkaigiri	11KV	Sainikpuri	23.00	23.40	00.40		11KV Polymer disc failed at RTC Colony near Second Bus Stop	No