

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1							
2	NLG	144	988		9							
3	MDK	107	933									
4	SDPT				1							
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	0	0	0	0	0	0	
	Grand Total	1082	6468	1	12	0	1	0	1	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.04.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kosgi	Kosgi	33KV	Narayanapet	03.10	04.00	00.50	E/L	33KV 2 No Pole Damaged	Kosgi	-

TSSPDCL - LMRC / Corporate office

Date: 25.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Konded	Chinna aadirala	11KV	Jadcherla	09.05	10.55	01.50		11Kv Insulator Failure Near Chinna Adirara(Vi).	-
1	NLG	Mukundapuram	Mukundapuram	11KV	Huzurnagar	06.20	10.23	04.03	E/L	Due to Tree branch	-
2		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	08.53	14.00	05.07	E/L	11Kv line snapped	-
3		Chedella	Chedella	11KV	Suryapet	04.05	06.25	02.20	E/L	11Kv Insulator failed	-
4		Koppole(K)	Bheemaram	11KV	Nalgonda	09.00	12.40	03.40	E/L	SS-2 11KV Line Insulatore Failur	-
5		Madgulapally	Kukkadam	11KV	Nalgonda	11.20	13.10	01.50	E/L	11KV Line Jumper Cutting	-
6		Ch.Mamidi	Velmakanne	11KV	Nalgonda	06.00	08.30	02.30	E/L	11KV Line Disc Cutting	-
7		Pazzur	Khaziramaram	11KV	Nalgonda	12.15	15.20	03.05	E/L	11KV Line AB Switch Fimail Cutting	-
8		MR.Gudem	Gangasanipally	11KV	Bhongir	14.00	16.15	02.15	OL	11 kv Insulator Failed at SS - 2 Near Gangasanipally Village	-
9		Velmajala	Kommaipally	11KV	Bhongir	10.25	14.10	03.45	OL	11 kv Line Snapped at Dealer Narsireddy Well & Jumper Open , 2 no's DTR's OFF. Near Velmaja Village. 3 Phase B/d Single Phase OK	-
1	SDPT	Bejjanki	Rws	11KV	Husnabad	13.20	16.10	02.50		BD,Insulator failure	-
1	RR S	Gaganpahad	Gaganpahad	11KV	RJNR	12.11	14.16	02.05	B/D	11KV Insulator failed at Jalpally	-