

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	0	14	0	14	0	14	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nuthankal	Yadavally	11KV	Suryapet	13.20	15.30	02.10	E/L	11KV Disc failed	No
2		Ananthagiri	Mogalaikota	11KV	Huzurnagar	03.20	05.30	02.10	E/L	11KV Jumper cut	No
3		Kandibanda	Gandi nagar thanda	11KV	Huzurnagar	13.57	16.40	02.43	E/L	11KV Line snapped	No
4		Thogarrai	Kapugallu	11KV	Huzurnagar	05.30	08.24	02.54	E/L	Tree branch fallen on the 11KV line	No
5		Chilukur	Kondapuram	11KV	Huzurnagar	09.35	11.10	01.35	E/L	11KV Jumper cut	No
6		Thurkapally	M.Gouraram	11KV	Nalgonda	12.30	14.50	02.20	E/L	HT/LT Line Cut	No
7		Gudapur	Raavigudem	11KV	Nalgonda	08.00	10.35	02.35	E/L	11KV Line disc failed	No
8		Mandollagudem	Nelapatla	11KV	Choutuppal	7:00	10:20	3:20	EL	11KV Line snapped near Nakkalagudem Village	No
1	MDK	SRD -Town-II	Balaji	11KV	Sangareddy	16:00	17:00	1:00		Jumper cut	No
1	RR S	APPA	Darga	11KV	RJNR	14:25	15:25	1:00		11KV Insulator failed at Himayathsagar village	No
2		NPA	Raghavendra Colony	11KV	RJNR	12.02	13.30	01.28		Tree branches fallen on 11KV line at Raghavendra colony SS-12 T/F	No
1	RR N	ICICI	Unique-I	11KV	Medchal	00.30	01.43	01.13		11KV Line AB switch sparked at Kemo Company	No
1	HYD S	Falaknuma	Chatrinaka	11KV	Charminar	19.35	21.35	02.00	EL,OL-Bph	Faulty 4No.DTR's loads of 11KV Lal Darwaza feeder	No
1	HYD C	Bathkammakunta	Saibaba Temple	11KV	Azamabad	07.45	09.05	01.20	OL-Rph	No Visible Fault	Arranged B/F on 11KV C.E Colony feeder