

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	2	3	2	3	2	0	0	
	Grand Total	1082	6468	4	4	4	4	4	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.02.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBN	Polepally	Jadcherla	33KV	Jadcherla	05.00	08.05	03.05	EL	Disc Failed and Replacement at University		NO
2	NLG	Kolanpaka	Sharajipet	33KV	Bhongir	10:42	11:57	1:15	O/L	33kv line phase to phase(Loose line) near Kolanpaka 132kv Sub-Station 2pole		
1	MDK	Kandi	Bharath Strips	33KV	Sangareddy	2:20	4:20	2:00		BD due to Conductor snapped		
1	RRN	132KV Medchal	33KV Medchal-I	33KV	Medchal	15.03	18.12	03.09		Tree Branches fallen on the 33KV Line near Druva Collage		

TSSPDCL - LMRC / Corporate office

Date: 07.02.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ravulapally	Kukkadam	11KV	Suryapet	14:00	16:30	2:30	E/L	11Kv Insulator flashover	No
2		Eduloor	Garlabaigudem	11KV	Nalgonda	13.45	16.40	02.55	E/L	11Kv Line cut near Village	No
1	HYD S	Seetharambagh	Dattatreya Nagar OH	11KV	Begumbazar	15.50	17.25	01.35	EL,OL-Bph	Cable fault	Arranged B/F on 11KV Dattatreya Nagar UG fdr
1	HYD C	Gudimalkapur	Navodaya Colony	11KV	Mehdipatanam	13.11	16.58	03.47	EL	Cable fault	Arranged B/F on 11KV A-1 Hotel feeder