

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	4	0	4	0	4	0	0	
	Grand Total	1082	6468	0	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Repala	Kalakova	11KV	Huzurnagar	06.00	08.15	02.15	EL	11 KV JUMPER CUT	-
2		Datharpally	Mallapur	11KV	Bhongir	11.28	14.50	03.22	EL	11kv Insulator fail Near Mallapur Village 3 Phase B/d Single Phase Ok	-
3		Yennaram	Suraram	11KV	Chouttuppall	15.00	16.50	01.50	EL	11KV Jumper Snapped Near Suraram Village	-
1	MDK	Gummadidala	Gummadidala Town	11KV	Patancheru	16.05	18.10	02.05		B/D due to Tree branches fallen on the line Gummadidala (V)	-
1	RR N	Shameerpet	Nalsar	11KV	Medchal	07.45	08.55	01.10	BD	Bird Fallen on 11KV Line at MRO office,Shameerpet	-
1	HYD N	Kalyan Nagar	Madhura Nagar	11KV	Banjarahills	15.36	17.10	01.34	EL	Cable End Kit failed at Corporation Bank	-