

Status Report on Breakdowns (Urban / Rural)

Urban

| S.No | Circle | No. of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | 1 | 1 | 1 | 1 | 1 | 1 | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | | | | | | | | | |
| | Total | 606 | 3055 | 1 | 1 | 1 | 1 | 1 | 1 | 0 | 0 | |

Rural

| S.No | Circle | No. of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|--------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | 1 | | 1 | | 1 | | | | |
| 2 | NLG | 144 | 988 | | 2 | | 2 | | 2 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 1 | 2 | 1 | 2 | 1 | 2 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 2 | 3 | 2 | 3 | 2 | 3 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 21.02.2019

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|-----------------------|---------------------------|
| 1 | MBNR | Balanagar | Thomidirekula | 33KV | Jadcherla | 16.15 | 19.40 | 03.25 | EL | 1No Disc Replacement & Break out Jumper Jointed Near Rubber Company | | - |
| 1 | RR N | 132KV Medchal | 33KV Medchal-I | 33KV | Medchal | 00.05 | 01.30 | 01.25 | BD | 33KV Jumpers cut & replacement at REVL Company | | - |

TSSPDCL - LMRC / Corporate office

Date: 21.02.2019

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | NLG | Cheedella | Thangellagudem | 11KV | Suryapet | 07.30 | 08.50 | 01.20 | E/L | Tree branch fallen on the line | - |
| 2 | | Repala | Repala | 11KV | Huzurnagar | 12.50 | 13.50 | 01.00 | E/L | Due 11Kv line cutted | - |
| 1 | RR N | Vemana colony | surksha enclave | 11KV | Kukatpally | 10.15 | 11.20 | 01.05 | EL/OL | HT line Cut near friends Colony weater Tank | - |