

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933		1		1		1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	9	3	9	3	9	0	0	
	Grand Total	1082	6468	3	11	3	11	3	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Penpahad	Anajipuram	11KV	Suryapet	14.00	15.30	01.30	E/L	11Kv Conductor Snapped	-
2		Dirincherla	Yallapuram	11KV	Huzurnagar	08.00	09.00	01.00	E/L	11Kv Jumper Cut	-
3		Gaddipally	Gaddipally	11KV	Huzurnagar	10.40	13.00	02.20	E/L	11Kv Conductor Snapped	-
4		Rajapeta	Rajapeta Agl	11KV	Bhongir	08.40	11.00	02.10	E/L	11Kv Jumer Cut In Rajapet (V) Near	-
1	MDK	Satwar	Cherakpally	11KV	Zaheerabad	07.30	09.40	02.10		BD due to Insulator failed	-
2	SDPT	NAGAPURI	POSANAPLLY	11KV	SDPT	10.20	12.15	05.16		BD MOV MANT FUALT	-
3		MARMAMULA	DHARMARAM	11KV	SDPT	14.30	19.30	11.46		BD 11 KV LINE ARE TANGLED	-
4		POTHARAM	KESHAPUR	11KV	SDPT	12.15	13.25	06.50		BD TREES IS FALLEN ON THE LT LINE	-
5		KOHEDA	SRIRAMULAPALLY	11KV	SDPT	07.10	08.43	02.36		BD 11 KV CONDUCTOR SNAPPED	-
1	RR S	Lanco Hills	Khajaguda	11KV	GCB	03.23	05.30	02.07	BD	Lorry Dashed 11KV Pole at Khajaguda Cheruvu (Back feeding from Nanakramguda feeder)	-
1	RR N	Jeedimetla-III	Back lighty Hyalam	11KV	Jeedimetla	10.45	11.45	01.00	EL /OL	11kv line AB Cable Endkit failure at Layland Bus Body Phase-V	-

TSSPDCL - LMRC / Corporate office

Date: 23.02.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Midjil	Madaram	33KV	Jadcherla	13.15	14.40	01.25	E/L	Conductor snapped at 132 KV SS Midjil	Madaram	-
2		Wanaparthi	Kothakota	33KV	Wanaparthi	07.29	10.20	02.51		33KV Conductor Snapped	Kothakota	-
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	10.20	12.50	02.30	E/L	33KV Jumper cut	Kethepally	-