

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	4	1	4	1	4	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.02.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Bibinagar	BP.Pally	33KV	Bhongir	10:15	12:45	2:30	OL	33 KV Jumper cut near Raghavapur Village	BP.Pally	No

TSSPDCL - LMRC / Corporate office

Date: 26.02.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kothapally	Peddamunigal	11KV	Devarakonda	22:00	6:00	8:00	E/L	Jumper cut	No
2		Kothapally	Peruvala	11KV	Devarakonda	00.45	07.00	06.15	E/L	Jumper cut	No
3		Nadigudem	Krishnanagar	11KV	Huzurnagar	07.20	10.35	03.15	EL	11KV Line snapped	No
1	MDK	Narayankhed	Jukal	11KV	Jogipet	9:00	12:00	3:00		Conductor snapped	No
1	RR N	Kompally	Jaibheri	11KV	Medchal	13:53	14:35	0:42		100KVA T/F Lighting arrester failed at Water Tank, Jaibheri Park	No
1	RR E	Singapur	RGK	11KV	Habsiguda	17:45	19:00	1:15		Line patrolling but no visible fault	No
2		Singapur	RGK	11KV	Habsiguda	19.40	20.20	00.40		Tree banches fallen on 11KV line at Venkatapuram Yadireddy Venture	No