

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	10	2	10	2	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.02.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Midjil	Madaram	33KV	Jadcherla	11.45	13.40	01.55	EL	Remove the Hanging Wire & Line Patrolling Done	Madaram	-
1	NLG	Ramannapet	Arror	33KV	Choutuppal	15.55	17.35	01.40	EL/OL	Due to Rain 33kv Insulator Fail In Golanpally (V)	Arror	-

TSSPDCL - LMRC / Corporate office

Date: 27.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dondapadu	Vajinepally	11KV	Huzurnagar	09.30	11.30	02.00	O/L	11Kv jumper cut	-
2		Palakaveedu	Bothalapalem	11KV	Huzurnagar	10.20	13.05	02.45	E/L	11Kv line cut	-
3		Pamanagundla	Pittampally	11KV	Nalgonda	04.40	07.30	02.50	E/L	AB switch jumper cut	-
4		Madgulapally	Dacharam	11KV	Nalgonda	06.05	10.15	04.10	E/L	Snake burned on 11KV line at SS-1	-
5		Mushampally	Mushampally	11KV	Nalgonda	10.00	11.00	01.00	E/L	11KV Jumper cut	-
6		Damaracherla	Wadapally	11KV	Miryalgudem	16.25	17.20	00.55	E/L	11Kv Cable Failed at Railway Track	-
7		Ramlingampally	Saiteja Indl	11KV	Bhongir	06.30	10.30	04.00	EL/OL	6no's 11kv Disc Fail & 11kv Pin Insulator Fail In chemical company B.Ramaram Villge(Fault in chemical Company Insid Balst)	-
1	RR N	Jeedimetla-III	USP Organic	11KV	Jeedimetla	05.10	06.50	01.40	EL /OL	11kv AB Cable Failure Near Standred glass Company at S S	-
1	HYD N	Jana Priya	I.O.L.	11KV	IV	01.25	02.35	01.10	EL	UG Cable fault at Don Basco School	-----
1	HYD S	Salarjung	Q.Q.Stadium	11KV	III	19.02	20.33	01.31	EL,OL	Cable fault near City College	Arranged B/F on 11KV Petlaburz fdr