

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	5	0	5	0	5	0	0	
	Grand Total	1082	6468	0	9	0	9	0	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ravulapally	Ravulapally	11KV	Suryapet	09.00	10.30	01.30	EL	Insulator failed	-
2		Edulur	parada	11KV	Nalgonda	06.00	09.00	03.00	EL	CT Probleam	-
3		Rayanguda	A.D.Pally	11KV	Nalgonda	09.30	10.30	01.00	EL	11KV line Jumper Cut	-
4		MR.Gudem	Indl	11KV	Bhongir	15.20	16.40	01.20	EL/OL	11kv Line Snapped at 33/11kv MR.Gudem Sub-station near 6th no Pole	-
5		Settipalem	Settipalem-1	11KV	Miryalaguda	01.05	07.40	06.35	EL	Bird Fallen on tha DTR	-
1	RR N	Kandlakoya	Kandlakoya	11KV	Medchal	15.10	17.10	02.00		11KV Line Cut and replaced at Function Hall,Kandlakoya	-
1	RR E	CRPF	Chenapur	11KV	Keesara	16.30	17.20	00.50		Line petrolling done no visoable falt found	-
1	HYD S	Karwan	Karwan	11KV	Begumbazar	08.20	09.50	01.30	EL,OL-Rph	Bird fault on lines at Ring Road, Karwan	-
2		Karwan	Jiyaguda OH	11KV	Begumbazar	08.25	10.20	01.55	EL,OL-Rph	5Way R.M.U Bus Bar fault at Pillar No.108	-