

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Malleboinpally	Malleboinpally	11KV	Jadcherla	07.50	09.30	01.40		Male And Female Contacts Fitting Work At SS.	-
1	NLG	Bopparam	M.K.Gudem	11KV	Suryapeta	07.20	08.40	01.20	E/L	Insulator flashover	-
2		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	06.30	08.50	02.20	E/L	Insulator failure	-
3		Pamanagundla	Pamanagundla AGL	11KV	Nalgonda	08.30	13.20	04.50	E/L	11KV Jumper cut	-
4		Thummalagudem	Bogaram	11KV	Bhongiri	05.00	08.00	03.00	E/L	HT/LT	-
5		Agamothkur	Bommakal	11KV	Miryalaguda	07.00	10.00	03.00	E/L	Tree fallen on line	-
1	HYD N	Raheja	Gafoor Nagar	11KV	Banjarahills	17.21	18.35	01.14	EL,OL-R&Yph	Squirrel fallen on lines at Plot No.70, Gafoor Nagar	Arranged B/F on 11KV Kummari Basti feeder