

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		13		13		13			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	0	19	0	19	0	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kavarampet	Town feeder	11kv	Jadcherla	06.35	08.27	01.52		DTR foulnt near grampanchayathi at kavarampet.	-
1	NLG	Alair	Ikkurthi	11kv	Bhongir	12.10	13;10	01.00	E/L	Tree Branches Fallen at SS 6 Ikkurthi Villge	-
2		Wangapally	Wangapally Agl	11kv	Bhongir	10.55	12.28	01.33	E/L	HT/LT near Wangapally Villge	-
3		Chamapur	Chamapur	11kv	Bhongir	12.00	15.20	03.20	E/L	11kv Insulator Fail Near Chamapur Villge	
4		Ramannapet	Siripuram	11kv	Choutuppal	00.00	09.10	09.10	E/L	Tree Branches Fallen at Line near Kommaiguda Road	
5		Choutuppal	Thangadapally	11kv	Choutuppal	04.30	11.00	06.30	E/L	11kv Jumper Open Near Chinthalakunta Villge	
6		Narayanapur	Kothagudem	11kv	Choutuppal	06.35	10.50	04.15	E/L	Tree Branches Fallen at Line near Kothagudem Villge	
7		Joloor	Peddaguem	11kv	Choutuppal	13.00	17.00	04.00	E/L	HT/LT near Jagathpally Villge	
8		Phanigiri	Anantharam	11kv	Suryapet	10.00	12.40	02.40	E/L	11Kv Conductor snapped	
9		Alingapuram	Alingapuram	11kv	Huzurnagar	11.22	13.14	01.52	E/L	11Kv Jumper Cut	
10		Mukundapuram	Somaram	11kv	Huzurnagar	08.00	09.40	01.40	E/L	11Kv Conductor snapped	
11		Arlagaddagudem	Mangalapally	11kv	Nalgonda	08.20	14.05	05.45	E/L	11 KV Line Insulator Failed	
12		Pullemla	Kondapuram	11kv	Nalgonda	09.30	11.40	02.10	E/L	11 KV Jumper Cut	
13		Nidmanoor	Shakapuram	11kv	Mirylaguda	03.10	07.15	04.05	E/L	Tree Branches Fallen at 11Kv Line	-
1	RR S	Kismathpur	LV Prasad	11kv	RJNR	03.20	04.50	01.30	B/D	Tree branches fallen on 11kv Line at LV prasad	-
1	RR N	LGM Pet	LGM Pet	11kv	Medchal	03.47	05.58	02.11	BD	Line patrolling done but no Visuable fault	-
1	RR E	VP Nagar	Deendayal Nagar	11kv	Sainikpuri	04.30	06.00	01.30		11Kv Over Head Cable fauilure at Hill Colony on Load Add on JK Colony feeder Vayupuri SS (LM Narsihma)	-
2		CRPF	Chenapur	11kv	Keesara	06.20	07.10	00.50		Kite rope fallen on 11kv line at malkaram	-
1	HYD C	I.T.I Mallepally	Afzal Sagar	11kv	Mehdipatnam	10.55	12.57	02.02	EL,OL-Bph	Cable fault at SS (3No. DTR's Kept Off)	Arranged B/F on 11KV Indira Nagar feeder

TSSPDCL - LMRC / Corporate office

Date: 12.01.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-