

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		1		1		1			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 16.01.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Mudireddypally	11KV	Mahabubnagar	01.30	08.30	07.00		Phase to Phase near Mudireddypally	No
1	NLG	Gaddipaly	Gaddipally	11KV	Huzurnagar	8:45	12:00	3:15	EL	Due to HT/LT fault occurred	No
1	MDK	Anrich Bollaram	Town-II	11KV	Patancheru	18:40	19:46	1:06		Jumper cut	No
1	RR S	Rajendranagar	Pahadi	11KV	Rajendranagar	17:25	18:20	0:55		11KV Line twisted at KK Function hall due to Kites fallen on 11KV line	No
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	22:10	23:30	1:20		11KV Line cut and replaced at Devarayamjal Village	No
1	RR E	Vasanthapuri	Sairam	11KV	Sainikpuri	13:35	14:20	0:45		Conductor Snapped	No
2		Moula-Ali	Kailasagiri	11KV	Sainikpuri	17.30	18.30	01.00		Jumper cut	No