

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	0	9	0	9	0	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kasarabadha	Ruplathanda	11KV	Suryapet	04.30	07.00	02.30	EL	Jumper cut	-
2		Alingapuram	Raghavapuram	11KV	Huzurnagar	03.30	07.30	04.00	EL	11 KV JUMPER CUT	-
3		Repala	Narsimhalagudem	11KV	Huzurnagar	08.30	11.20	02.50	OL	11 KV LINE SNAPPED	-
4		Gudapoor	Singaram	11KV	Nalgonda	06.30	08.50	02.20	E/L	11 KV Line Insulator Failed	-
5		Yerraram	Kamapally	11KV	Devarakonda	21.00	08.00	11.00	E/L	AB Switch Male & Female Fault	-
6		Kothapally	Kasurajupally	11KV	Devarakonda	21.00	11.00	14.00	E/L	11 Line Cutt	-
7		Bondugula	Bondugula Agl	11KV	Bhongiri	07.45	10.10	02.25	EL	100 KVA DTR Fail In SS 47 Near Bondugula Villge	-
1	RR S	Balaji Nagar	Serena Estate	11KV	Kondapur	13.20	18.10	04.50	BD	11kv UG-Cable damagaed at Serena Estate Church	-
1	RR N	Laxmapur	MC Pally	11KV	Medchal	15.00	16.00	01.00	BD	Bird fallen on the 11KV Line at Gopal Reddy Bhaavi	-

TSSPDCL - LMRC / Corporate office

Date: 19.01.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD N				NIL							-
8	HYD S				NIL							-
9	HYD C				NIL							-