

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	9	1	9	1	9			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.01.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramapuram	Mellacheruvu	33KV	Huzurnagar	07.30	10.30	03.00	EL	33 KV DISK FAILED	Mellacheruvu	-

TSSPDCL - LMRC / Corporate office

Date: 21.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole(K)	Beemavaram	11KV	Nalgonda	06.00	09.00	03.00	EL	11 KV Line Insulator failed	-
2		Chedella	Nelamarri	11KV	Suryapet	08.50	10.45	01.55	EL	Jumper cut	-
3		Nagaram	Machireddypally	11KV	Suryapet	09.00	11.50	02.50	EL	Insulator flashover	-
4		Alingapuram	Chennaipalem	11KV	Huzurnagar	15.00	17.10	02.10	EL	11 KV LINE SNAPPED	-
5		N B Gudem	Redlakunta	11KV	Huzurnagar	07.30	10.00	03.30	EL	33 KV DISK FAILED	-
6		Kondamadugu	Kepal	11KV	Bhongir	09.25	10.35	01.10	EL	Near By Feeders HT/HT Phase to Phase near Saibaba Tempul Kondamadugu Villge	-
7		Kondamadugu	Nemaragomlla	11KV	Bhongir	09.25	10.35	01.10	EL	Near By Feeders HT/HT Phase to Phase near Saibaba Tempul Kondamadugu Villge	-
8		Solepet	Ramulthanda	11KV	Bhongir	12.35	14.00	01.25	EL	V Casram Clamp Shat Circuit	-
9		Y.gutta	Town	11KV	Bhongir	07.50	08.30	00.40	EL	Tree Branches Fallen In Line near Vadaigudem Villge	-
1	MDK	Narayankhed	Narayankhed-II	11KV	Jogipet	08.20	11.10	02.50		B/D Due to Conductor Snapped	-
1	RR S	Balajinagar	Serena Estates	11KV	Kondapur	15.53	22.45	06.52	BD	11KV UG Cable Damaged near Shishu Mandir School at Brand Factory.	-