

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	10	2	10	2	10	0	0	
	Grand Total	1082	6468	3	11	3	11	3	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.01.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Veldanda	33KV	Nagarkurnool	07.25	09.20	01.55	E/L&O/L	No visible fault	Veldanda	No
1	NLG	Ramapuram	Thogarrai	33KV	Huzurnagar	9:00	12:15	3:15	EL/OL	33 KV Conductor snapped	Thogarrai	No
1	HYD S	132KV Imlibun	Industrial Area (Idle)	33KV	Chilalguda	08.40	09.20	00.40	EL,OL	End kit fault at Golnaka	Industrial Area (Idle)	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Annasagar	Tatikonda	11KV	Jadcherla	07.15	08.15	01.00		Bird died on the 11KV line near Tatikonda (V)	No
1	NLG	Y.Singaram	Singaram	11KV	Huzurnagar	10:30	13:00	2:30	E/L	11Kv Conductor snapped	No
2		Mattampally	Allipuram	11KV	Huzurnagar	15.00	16.30	01.30	E/L	11Kv Conductor snapped	No
3		Munagala	Barakathgudem	11KV	Huzurnagar	04.20	07.00	02.40	E/L	11Kv Conductor snapped	No
4		Ch.Mamidid	Velmakanne	11KV	Nalgonda	09.30	11.40	02.10	E/L	11KV Line Insulator Failed	No
5		Mushampally	Mushampally	11KV	Nalgonda	10.30	14.50	04.20	E/L	11KV Jumper Cut	No
6		Padamatipally	Iddampally	11KV	Devarakonda	12.30	13.30	01.00	O/L	11KV Line Cutt	No
7		VK Palem	Ilapuram	11KV	Miryalguda	00.00	18.00	18.00	E/L	5No.Poles Damage due to Tipper Lorry hitting	No
8		MR.Gudem	Baswapur	11KV	Bhongir	4:20	12:00	7:40	E/L	11KV Baswapur feeder CT fail Single Phase OK	No
1	MDK	Fasalwadi	MNR	11KV	Sangareddy	15:46	17:05	1:19		Bird fallen on line near MNR Tower	No
1	RR N	Town Medchal	Balaji Nagar	11KV	Medchal	17:10	18:20	1:10		Tree fallen on the 11KV line at Balaji nagar	No