

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	3	3	3	3	3			
2	NLG	144	988		28		28		28			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	33	3	33	3	33	0	0	
	Grand Total	1082	6468	3	36	3	36	3	36	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.01.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Palkonda	Kodur	33KV	Mahabubnagar	00.25	10.10	09.45		Jumper snapped at Dharmapur (V)	Kodur	-
2		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	06.56	09.20	02.24		LA Jumper Removed at 132KV Nagarkurnool	Peddakothapally	-
3		Kothur	Sangem	33KV	Shadnagar	12.55	14.35	01.40	E/L	Jumper Replaced at Temple	Sangem	-

TSSPDCL - LMRC / Corporate office

Date: 29.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pedda Revally	Hemajipur	11KV	Jadcherla	00.00	07.30	07.30		11KV Disk fail near Balaji gutta thanda	-
2		Pomal	Ammapur	11KV	Jadcherla	00.00	10.00	10.00		11KV Disk fail near Ammapur	-
3		Mothiganapur	Mothiganapur	11KV	Jadcherla	00.00	11.40	11.40		11KV Disk fail near Mothiganapur	-
1	NLG	Kethepally	Inupamula	11KV	Nalgonda	09.15	13.20	04.05	E/L	Tree Cutting	-
2		Induloor	Parada	11KV	Nalgonda	06.36	12.20	05.44	E/L	11 KV Line Insulator Failure	-
3		Rayanaguda	A.d.Pally	11KV	Nalgonda	02.00	07.00	05.00	E/L	HT/LT Melting	-
4		Palem	Bopparam	11KV	Nalgonda	01.00	07.30	06.30	E/L	HT/LT Melting	-
5		Palem	Palem	11KV	Nalgonda	07.30	09.30	02.00	E/L	11 KV Line Jumper Cut	-
6		Palem	Ogodu	11KV	Nalgonda	08.40	11.00	02.20	E/L	11 KV Line Insulator Failure	-
7		Katangur	Kalimera	11KV	Nalgonda	03.00	08.30	05.30	E/L	HT/LT Melting Hevy Rain	-
8		Eduloor	Naragudem	11KV	Nalgonda	10.00	11.00	01.00	E/L	11 KV Line Jumper Cut	-
9		Marriguda	Y.G.Pally	11KV	Devarakonda	06.00	07.00	01.00	E/L	Tree Follan	-
10		Devarakonda	Mynampally	11KV	Devarakonda	02.00	09.00	07.00	E/L	1 Nos pole Broken	-
11		Teldevarapally	Ghanapuram	11KV	Devarakonda	03.00	08.00	05.00	E/L	11Kv Line Cutt & Insulator failed	-
12		Ghanapuram	G.B.Pally	11KV	Devarakonda	05.00	07.00	02.00	E/L	HT/LT	-
13		Puttamgandi	Vaddipatla	11KV	Devarakonda	05.30	10.00	04.30	E/L	Jumper Cutt	-
14		Pochampally	Chinnamandapuram	11KV	Devarakonda	06.00	08.30	02.30	E/L	11 Kv Insulator failed	-
15		Chinthapally	Vinjamoor	11KV	Devarakonda	07.00	11.30	04.30	E/L	Jumper Cutt	-
16		Nuthankal	Polumalla	11KV	Suryapet	08.20	10.30	02.10	E/L	Insulator flashover	-
17		Penpahad	Macharam	11KV	Suryapet	07.00	09.50	02.50	E/L	Conductor snapped	-
18		B Chandupatla	B chandupatla	11KV	Suryapet	05.00	07.45	02.45	E/L	insulator failed	-
19		Ravulapally	Thurpugudem	11KV	Suryapet	08.00	10.20	02.20	E/L	Jumper cut	-
20		Alingapuram	Channaipalem	11KV	Huzurnagar	08.00	11.00	03.00	EL	Due to 11Kv Jumper cutted	-
21		Y.Singaram	Y.Singaram	11KV	Huzurnagar	07.30	09.00	01.30	EL	Due to 11Kv Disk failure	-
22		Repala	V R Puram	11KV	Huzurnagar	05.00	08.30	03.30	EL	Due to 11Kv Jumper cutted	-
23		Siripuram	Vallapuram	11KV	Huzurnagar	04.55	08.00	03.05	EL	Due to 11Kv insulator failure	-
24		Ravipahad	Burkacherla	11KV	Huzurnagar	06.05	09.20	03.15	EL	Due to tree branch fall on 11Kv line	-
25		Sirikonda	Balluthanda	11KV	Huzurnagar	06.40	10.00	03.20	EL	Due to 11Kv Disk failure	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
26		Addagudur	Dharmaram	11KV	Bhongir	04.00	09.00	05.00	EL	Due to Heavy Rain 3 Phase Berak Down single phase ok 10kva DTR Fail In Laxmaigudem Villge	-
27		Paladugu	Duppally	11KV	Bhongir	03.30	09.30	06.00	EL	11kv Insulator Fail In SS-8 Dupally Villge	-
28		Puligilla	Puligilla	11KV	Choutuppal	03.00	08.00	05.00	EL	Due to Heavy Rain 11kv Disc Fail Near Kishna Murthi Rice mill Puligilla Villge	-
1	SDP	Guggilla	Thimmaipally	11KV	Husnabad	12.05	14.25	02.20		Break Down No visible fault	-
2		Akunoor	Akunoor Agl	11KV	Husnabad	00.00	16.00	16.00		Break Down Jumper cut	-
1	HYD N	I.D.P.L.	Wonder Plast	11KV	VI	17.45	19.45	02.00	EL,OL	CT PT failed at Plot No.34, SVCIE	-
1	HYD C	Public Garden	Nampally Railway Station	11KV	I	02.27	03.36	01.09	EL,OL-Rph	Jumper cut at Nampally Rly Station	-
2		Indira Park	Airforce-II	11KV	I	08.55	18.40	09.45	EL	Cable fault at Airforce Quarters	Arranged B/F on 11KV Airforce-I fdr