

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 29.01.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Narayanapet	02.40	06.25	03.45	O/L	Tree fallen at Thangidi village	Krishna	No
2		leeza	Mitta Doddy	33KV	Gadwal	02.11	06.46	04.35	E/L	No visibul fault	Mitta Doddy	No
3		Kodangal	Hamsanpally	33KV	Vikarabad	05.20	06.50	01.30	E/L	No visibul fault	Hamsanpally	No

TSSPDCL - LMRC / Corporate office

Date: 29.01.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chedella	Thangellagudem	11KV	Suryapeta	13:20	15:40	2:20	E/L	11KV Conductor Snapped	No
2		Phanigiri	Phanigiri	11KV	Suryapeta	13.05	14.55	01.50	E/L	Conductor Snapped	No
3		Motakondur	Motakondur	11KV	Bhongiri	06.30	08.20	01.50	E/L	11KV Line Snapped	No
4		Mothkur	Aregudem	11KV	Bhongiri	05.00	08.00	03.00	E/L	11KV Disc failure	No
5		Choutupal	Thangedipally	11KV	Bhongiri	12.40	14.30	01.50	E/L	11KV Line Snapped	No
6		Palakeedu	Nagireddy gudem	11KV	Huzurnagar	07.00	10.00	03.00	E/L	11KV Disc & Conductor Snapped	No
7		Janpahad	Janpahad	11KV	Huzurnagar	7:00	10:30	3:30	E/L	11KV Line Snapped	No
1	RR N	Kompally	Kompally	11KV	Medchal	20:16	20:55	0:39		11KV Line Touched to Crossarm at Jaibheri Park	No