

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 30.01.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Kolanpaka	Alair	33KV	Bhongir	10:05	11:40	1:35	EL	33kv Jumper Cut In Kolanpaka 132kv Sub-station near pole no 2	Alair	No
1	MDK	Jogipet	Dakur	33KV	Jogipet	16:25	19:30	3:05		BD due to Pole damaged	Dakur	No
1	HYD C	132KV Asif Nagar	Kulsumpura	33KV	Asif Ngr	01.00	01.13	00.13	EL,OL-Rph	Cable fault at Opp. Kings Palace Function Hall, Laxmi Nagar X Road	Kulsumpura	Loads transferred onto 132KV Imlibun SS via 33KV Gosha Mahal feeder

TSSPDCL - LMRC / Corporate office

Date: 30.01.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Alwan pally	11KV	Jaddcherla	12.28	13.50	01.22		11KV Pole Damaged near Shankaraiahpally (V)	No
1	NLG	Penpahad	Dubbathanda	11KV	Suryapet	9:00	11:40	2:40	E/L	11KV Conductor snapped	No
2		Koyyalagudem	Koyyalagudem Agl	11KV	Choutuppal	06.10	09.40	03.30	EL	11KV Line snapped near Yellagiri Village	No
1	RR S	Rajendranagar	Pahadi	11KV	Rajendranagar	18:20	19:20	1:00	B/D	11KV Cable kit failed & replaced at Paradise Function Hall	No
1	RR E	Yadgarpally	Cheryala	11KV	Keesara	3:20	6:20	3:00		Insulator failed at cheryala Kaman	No