

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		8		8		8			
6	RR(N)	54	550	2	40	2	40	2	40			
7	RR(E)	168	403		26		26		26			
8	Hyd	194	1044		139		139		139			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>213</b>	<b>2</b>	<b>213</b>	<b>2</b>	<b>213</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	14	2	10	2	10	2	4		4 Nos. 33KV Pending
2	NLG	144	988		14		14		14			
3	MDK	107	933	14		8		8		6		6 Nos. 33KV Pending
4	SDPT			10	5	7	3	7	3	3	2	3 Nos. 33KV Pending 2 Nos. 11KV Pending
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>38</b>	<b>21</b>	<b>25</b>	<b>19</b>	<b>25</b>	<b>19</b>	<b>13</b>	<b>2</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>40</b>	<b>234</b>	<b>27</b>	<b>232</b>	<b>27</b>	<b>232</b>	<b>13</b>	<b>2</b>	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Jadcherla	33KV	Mahabubnagar	19.45	22.15	02.30	E/L	Due to rain	Jadcherla	Back feed supply taken to 33KV Polepally feeder at 22:15Hrs
2		Palkonda	Kodur	33KV	Mahabubnagar	20.04	22.20	02.16	E/L	33KV Line Phase to Phase	Kodur	
3		Midjil	Madaram	33KV	Jadcherla	20.15	22.35	02.20	E/L	No Visible Fault	Madaram	
4		Polepally	Konded	33KV	Jadcherla	20:24	21:50	01.26	E/L&O/L	33KV Pin Insulator Replacement	Konded	
5		Maddur	Pallerla	33KV	Narayanpet	22:40	0:00	01.20	E/L	Not Rectified	Pallerla	
6		Maddur	Vepoor	33KV	Narayanpet	22:40	0:00	01.20	E/L	Not Rectified	Vepoor	
7		Ghanpur	Lattupally	33KV	Wanaparthy	21:19	0:00	02.41	E/L	Not Rectified	Lattupally	
8		Ghanpur	Kamaluddinpur	33KV	Wanaparthy	20:58	0:00	03.02	E/L	Not Rectified	Kamaluddinpur	
9		Alampur	Shanthinagar-I	33KV	Gadwal	8:10	15:40	07.30	E/L	Pole leaned Fallon 11KV line near Bonkur Village	Shanthinagar-I	
10		Alampur	Shanthinagar-II	33KV	Gadwal	21:40	22:10	00.30	E/L	Due to rain	Shanthinagar-II	Back feed supply taken to 33KV Shanthinagar-I feeder at 22:10Hrs
11		Achampet	Veltoor	33KV	Nagarkurnool	11:45	13:50	02.05	E/L	Tree Fallen on the Line at Koratikal(V)	Veltoor	
12		Shadnagar	Shadnagar	33KV	Shadnagar	17:05	19:00	01.55	E/L	R Phase Pin insulator failed at Devarsree company	Shadnagar	
13		Shadnagar	SALASAR(Scan)	33KV	Shadnagar	18:40	22:30	03.50	E/L	R Phase Pin insulator failed at Devarsree company	SALASAR(Scan)	
14		Sri Rangapur	Scan Energy	33KV	Shadnagar	20.30	21.45	01.15	E/L	Due to Rain No Visible Fault	Scan Energy	
1	MDK	Sadasivpet	Manjeera	33KV	Sangareddy	20:30	0:00	3:30		Not Rectified	Manjeera	
2		Pashamailaram	EPIP	33KV	Sangareddy	16.15	18.15	02.00		BD due After petrolling no fault at found	EPIP	
3		Pashamailaram	Manjeera	33KV	Sangareddy	18.10	20.55	02.45		BD due to	Manjeera	
4		Pashamailaram	BOC	33KV	Sangareddy	20.45	00.00	03.15		Not Rectified	BOC	
5		Pashamailaram	APL IV	33KV	Sangareddy	16.50	18.35	01.45		BD due Tree fall	APL IV	
6		Pashamailaram	Suven life science	33KV	Sangareddy	03.50	06.58	03.08		BD due to cable kit failed	Suven life science	
7		Zaheerabad	Chota Hyderabad	33KV	Zaheerabad	15.44	17.30	01.46		BD due to Disc failed	Chota Hyderabad	
8		Gummadidala	AFA	33KV	Patancheru	20.35	00.00	03.25		Not Rectified	AFA	
9		R.C.Puram	Girdhar Ispat	33KV	Patancheru	20.05	00.00	03.55		Not Rectified	Girdhar Ispat	
10		Bollaram	Bollaram - II	33KV	Patancheru	16.15	20.55	04.40		BD due to Bus Jumper cut	Bollaram - II	
11		Bollaram	VIF	33KV	Patancheru	16.15	20.55	04.40		BD due to Bus Jumper cut	VIF	
12		Bollaram	Shathavahana	33KV	Patancheru	16.10	20.20	04.10		BD due to Conductor snapped & Jumper cut	Shathavahana	
13		Narayankhed	Sirgapur	33KV	Jogipet	21.20	00.00	02.40		Not Rectified	Sirgapur	
14		Singoor	Mudmanik	33KV	Jogipet	18:45	0:00	5:15		Not Rectified	Mudmanik	
1	SDPT	Siddipet	Narayanraopet	33KV	Siddipet	21:30	23:45	2:15		Heavy wind and rain	Narayanraopet	
2		Siddipet	Narayanraopet	33KV	Siddipet	23.45	00.00	00.15		Not Rectified	Narayanraopet	
3		Siddipet	Peddakodur	33KV	Siddipet	19.45	23.45	04.00		Heavy wind and rain	Peddakodur	
4		Siddipet	Thornala	33KV	Siddipet	19.30	20.05	00.35		Heavy wind and rain	Thornala	
5		Habsipur	Dubbak	33KV	Siddipet	17.25	19.10	01.45		Heavy wind and rain	Dubbak	
6		Habsipur	Peddachikode	33KV	Siddipet	17.25	20.25	03.00		Heavy wind and rain	Peddachikode	
7		Habsipur	Pothareddypet	33KV	Siddipet	17.25	20.30	03.05		Heavy wind and rain	Pothareddypet	
8		Habsipur	Ragothampally	33KV	Siddipet	17.20	20.30	03.10		Heavy wind and rain	Ragothampally	
9		Chandlapur	Jakkapur	33KV	Siddipet	18.50	00.00	05.10		Not Rectified	Jakkapur	
10		Mustyala	Komuravelly	33KV	Husnabad	16.50	00.00	07.10		Not Rectified	Komuravelly	
1	RR N	132KV Medchal	Santha Bio Tech	33KV	Medchal	5:30	10:30	5:00		33KV Pole Replaced at Check Post	Santha Bio Tech	
2		132KV Medchal	Steelmill	33KV	Medchal	16.14	20.15	04.01		33KV Jumper cut and replaced in SS	Steelmill	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Addakal	Thimmaiaply	11KV	Jadcherla	02.40	09.15	06.35		11KV Insulator failed near Thimmaipally	No
2		Addakal	Gudibanda	11KV	Jadcherla	02.40	08.00	05.20		11KV Jumper cut near Gudibanda	No
1	NLG	Cheedella	Gajula malkapuram	11KV	Suryapeta	14:00	15:50	1:50	E/L	Conductor snapped	No
2		Dondapadu	Dondapadu	11KV	Huzurnagar	09.20	12.15	02.55	EL	Due to 11KV line cut	No
3		Repala	Repala	11KV	Huzurnagar	18.00	19.00	01.00	EL	Due to 11KV line snapped	No
4		Koppole(K)	Kopolu	11KV	Nalgonda	06.00	10.00	04.00	EL	11 KV Line Jumper cut	No
5		Arlagaddagudem	Chinna Suraram	11KV	Nalgonda	03.00	06.50	03.50	EL	HT/LT line milting	No
6		Sh.Gowraram	Gurajala	11KV	Nalgonda	14.00	16.10	02.10	EL	11 KV Line Disc failure	No
7		Chandupatla	Chandupatla	11KV	Bhongir	06.00	07.45	01.45	OL	HT/LT Near Chandupatla Village	No
8		Sharajipet	Kolluru	11KV	Bhongir	05.00	10.50	05.50	OL	SS-5 Jumper Cut & 2 No's LT Pole Dammaged Near Kolluru Village	No
9		Motakondur	Vartoor	11KV	Bhongir	10.00	18.30	06.30	OL	3 Different Places HT/LT & Single Phase DTR Fault Near Vartoor Village	No
10		Ambala	Parupally	11KV	Bhongir	16.35	18.20	01.45	EL	Tree branchess fallen at line near Parupally Village	No
11		D.Nagaram	D.Nagaram Indl	11KV	Choutuppal	06.10	08.40	02.30	EL	Copper Patti Cut at N-Teck Company near D.Nagaram Village	No
12		D.Nagaram	Pipalpad Agl	11KV	Choutuppal	01.45	08.02	05.17	OL	HT/LT near Pipalpad Village	No
13		Narayanapur	Melacheruvu	11KV	Choutuppal	06.30	08.00	01.30	EL	SS-56 Solid core insulator failed at Singapalla Mangaiah well near Melacheruvu	No
14		BP.Pally	Narayanagiri	11KV	Choutuppal	3:45	8:45	5:00	OL	HT/LT near Narayanagiri Village	No
1	SDPT	Akunoor	Dommata	11KV	Husnabad	15:00	0:00	9:00		Not Rectifed	
2		Pandilla	Pandilla Rural	11KV	Husnabad	20.00	00.00	04.00		Not Rectifed	
3		Pandilla	Potlapally	11KV	Husnabad	19.00	20.00	01.00		Jumper cut	No
4		Husnabad-2	Husnabad Town-3	11KV	Husnabad	20.25	21.40	01.15		BD due to rain	No
5		Thotapally	Thotapally (R)	11KV	Husnabad	6:10	7:25	1:15		Insulator failure	No
1	RR S	Kattedan-II	Ravi foods	11KV	RJNR	16:07	17:53	1:46		Bird Fallen on 11kv Line at Jaibhavani company	No
2		Gaganpahad	Pelicon rubber	11KV	RJNR	17.12	19.45	02.33		Tree Branches Fallen on 11kv Line at andhra liquor company	No
3		MD Pally	Palle cheruvu	11KV	RJNR	19.00	20.40	01.40		Tree Branches Fallen on 11kv Line at Pallecheruvu	No
4		Nanakramguda	Gowlidoddi	11KV	Gachibowli	16.43	19.04	02.21		Due to heavy wind and rain, 11kv LABS Opened at Journalist colony, Line petroling, Feeder test charged , Feeder OK	No
5		Nanakramguda	Church	11KV	Gachibowli	16.47	18.40	01.53		Due to heavy wind and rain, 11kv LABS Opened at Sreeram Nagar School , church line, 11kv Pin-insulator failed at Sreeram Nagar school backside	No
6		Nanakramguda	TNGO's Colony	11KV	Gachibowli	16.57	18.20	01.23		Due to heavy wind and rain	No
7		Nanakramguda	TNGO's Colony	11KV	Gachibowli	19.56	21.03	01.07		Due to heavy wind and rain, LABS Opened at Alay-baley X-road, 75% feeder charged Ok	No
8		ESCI	NCC	11KV	Kondapur	16:48	17:58	1:10		11kv DTR bush rod LTA Line cut at Istha Hotel,South India Shoping mall backside	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Somashila	Sheshadrinagar	11KV	Kukatpally	16:40	18:20	1:40		Construction Stick Fallen Removed the 11kv line at Allwyn Colony	No
2		Prashanthi	Mythrinagar	11KV	Kukatpally	16.30	17.55	01.25		Tree branchesh Removed at Vidhya Press , Kukatpally	No
3		Vemana Colony	Friends Colony	11KV	Kukatpally	19.19	21.54	02.35		160KVA T/F HG Fuse Insulater Failure at Laxmi Builder apt , Friends Colony	No
4		Jeedimetla-III	Ramreddy Nagar	11KV	Jeedimetla	16.38	19.15	02.37		Due to Rain & Wind	No
5		Jeedimetla-IV	Auto Stand	11KV	Jeedimetla	07.14	08.18	01.04		11kv line Pininsulater Failure at Auto Stand	No
6		Jeedimetla-IV	AAImatha	11KV	Jeedimetla	16.34	19.28	02.54		Tree branchesh fallen the 11kv line at AAImatha	No
7		Jeedimetla-IV	Venkatadri	11KV	Jeedimetla	16.34	18.04	01.30		Tree branchesh fallen the 11kv line at AAImatha	No
8		Jeedimetla-IV	Bhagyalaxmi	11KV	Jeedimetla	16.34	19.14	02.40		Tree branchesh fallen the 11kv line at AAImatha	No
9		Jeedimetla-IV	Auto Stand	11KV	Jeedimetla	16.34	18.04	01.30		Tree branchesh fallen the 11kv line at AAImatha	No
10		Jeedimetla-IV	Axies	11KV	Jeedimetla	16.34	21.48	05.14		Tree branchesh fallen the 11kv line at Sneha Bar , Gappala Basthi	No
11		Jeedimetla-IV	Tagoure	11KV	Jeedimetla	16.34	22.58	06.24		Tree branchesh Fallen the 11kv line at Sri sai Company & Jumper Snapped in SS	No
12		Jeedimetla-I	phase-II	11KV	Jeedimetla	17.35	22.35	05.00		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
13		Jeedimetla-I	Subhshnagar	11KV	Jeedimetla	17.35	22.35	05.00		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
14		Jeedimetla-I	phase-I	11KV	Jeedimetla	17.35	22.35	05.00		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
15		Jeedimetla-I	APIIC	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
16		Jeedimetla-I	Nitco	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
17		Jeedimetla-I	Maheshwari	11KV	Jeedimetla	17.35	22.35	05.00		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
18		Jeedimetla-I	phase-V	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
19		Jeedimetla-I	Raghava	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
20		Jeedimetla-I	CS Wires	11KV	Jeedimetla	17.35	22.35	05.00		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
21		Jeedimetla-I	HMT Socity	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
22		Jeedimetla-I	Thirumala	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
23		Jeedimetla-I	Sudharshan Drugs	11KV	Jeedimetla	17.35	19.00	01.25		Due to Rain & Wind {Tree branchesh fallen the 11kv line }	No
24		Jagathgiri Gutta	IDA Jagathgiri Gutta	11KV	Medchal	17.30	20.00	02.30		11KV Line cut & Replaced at Devamma Basti	No
25		Jagathgiri Gutta	Jagathgiri Gutta	11KV	Medchal	17.30	19.00	01.30		Metirial Fallen on 11KV Line at Maisamma nagar	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
26		Jagathgiri Gutta	Shiridi Hills	11KV	Medchal	17.30	19.00	01.30		Tree Fallen on 11KV Line at Jagathgiringutta	No	
27		Subhash Nagar	Gayatri nagar	11KV	Medchal	16.35	18.50	02.15		Tree fallen on the 11KV Line at TNR Function Hall	No	
28		Subhash Nagar	Jayaram nagar	11KV	Medchal	16.35	20.40	04.05		Tree fallen on the 11KV Line at SBI Bank, Vasudha Apartment	No	
29		Subhash Nagar	Jeedimetla	11KV	Medchal	16.35	17.52	01.17		Tree fallen on the 11KV Line at Green Park	No	
30		Subhash Nagar	Meenakshi	11KV	Medchal	16.35	17.44	01.09		Tree fallen on the 11KV Line at Meenkshi	No	
31		Subhash Nagar	Pragatools	11KV	Medchal	16.35	18.47	02.12		160KVA T/F Brass Patti cut and replaced at BHEL	No	
32		Subhash Nagar	Ramraj nagar	11KV	Medchal	16.35	17.55	01.20		Tree fallen on the 11KV Line at Los Vegas Hotel	No	
33		Subhash Nagar	Suchitra	11KV	Medchal	16.35	18.15	01.40		Tree fallen on the 11KV Line at TNR Garden	No	
34		Chintal	Ganesh Nagar	11KV	Medchal	16.40	18.40	02.00		Tree fallen on the 11KV Line at Ganesh Nagar	No	
35		HMT	Manikya Nagar	11KV	Medchal	17.00	19.30	02.30		Tree fallen on the 11KV Line at Indrasingh Nagar	No	
36		Subhash Nagar	Bank Colony	11KV	Medchal	16.35	20.55	04.20		11KV Line Cut and replaced at Modi Builders	No	
37		Subhash Nagar	Padma Nagar	11KV	Medchal	16.35	17.27	00.52		Tripped on EL Indication ( Due to heavy wind & Rain)	No	
38		Subhash Nagar	Saibaba nagar	11KV	Medchal	16.35	18.20	01.45		Cloth fallen on the 11KV Line at Trinidhi School	No	
39		HMT	Ganesh Nagar	11KV	Medchal	17.00	21.40	04.40		No visible fault	No	
40		Thurkapally	Yadaram	11KV	Medchal	13:52	15:20	1:28		11KV Pin Insulator failed at MBR Venture	No	
1		RR E	NGRI	HMT	11KV	Habsiguda	16:40	18:00	1:20		Tree fallen on 11kv line Puja hospital Hmt nagar Opp	No
2			Sai nagar	Saraswathi nagar	11KV	Habsiguda	17.50	18.25	00.35		11K V jumper cut at Saraswathi nagar	No
3			Sai nagar	RNS	11KV	Habsiguda	17.55	18.45	00.50		LT line cut at Bolliguda	No
4			Mallapur	IDA mallapur	11KV	Habsiguda	16.40	18.45	02.05		Tree fallen on 11kv line Guddi paint company	No
5			Mallapur	Noma	11KV	Habsiguda	16.40	18.50	02.10		Tree fallen on 11kv line Baba nagar	No
6	Nacharam		Bhagya nagar	11KV	Habsiguda	18.55	20.17	01.22		Tree fallen on 11kv line Telephone exchange	No	
7	Nacharam		Thunagabhara	11KV	Habsiguda	18.55	21.39	02.44		Tree fallen on 11kv line Nacharam main road	No	
8	Nacharam		Nagarjunna	11KV	Habsiguda	18.03	21.00	02.57		Tree fallen on 11kv line Nacharam Road no 16.	No	
9	Nacharam		Multisteel	11KV	Habsiguda	19.49	20.20	00.31		Tree fallen on 11kv line Nacharam Road no 07	No	
10	Sainikpuri		Saipuri	11KV	Sainikpuri	16.45	19.20	02.35		Tree fallen on 11Kv line at Saipuri	No	
11	Sainikpuri		Vijayapuri	11KV	Sainikpuri	16.45	21.10	04.25		Pole Dammage on Tree fallen on 11Kv line at Vijayapuri	No	
12	Sainikpuri		Sainikpuri	11KV	Sainikpuri	16.45	22.30	05.45		Tree fallen on 11Kv line at Sainikpuri	No	
13	Yapral		Yapral	11KV	Sainikpuri	06.35	07.50	01.15		Tree branches fallen on 11Kv line Goverdhanpuri	No	
14	Yapral		Govt School	11KV	Sainikpuri	17.25	18.00	00.35		Tree fallen on 11Kv line at Yapral	No	
15	Kushaigguda		Kushaigguda	11KV	Sainikpuri	17.40	18.40	01.00		Tree branches on 11Kv line at Kushaiguda	No	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
16		Kushaigguda	NN Colony	11KV	Sainikpuri	17.40	18.40	01.00		Tree branches on 11Kv line at Kushaiguda	No
17		Kushaigguda	Sri Ram Nagar	11KV	Sainikpuri	17.40	18.50	01.10		Tree branches on 11Kv line at Srinivasa Nagar	No
18		Kushaigguda	Rukminipuri	11KV	Sainikpuri	17.40	19.00	01.20		Tree branches on 11Kv line at Srinivasa Nagar	No
19		Kushaigguda	Saibaba Temple	11KV	Sainikpuri	17.40	19.00	01.20		Tree fallen on 11Kv line at ECIL	No
20		Kushaigguda	AS Rao Nagar	11KV	Sainikpuri	17.40	20.40	03.00		Tree branches on 11Kv line at AS Rao Nagar Nagar	No
21		NN Colony	Jai Jawan	11KV	Sainikpuri	18.03	19.30	01.27		11Kv Disk failure at Jiyareddy Nagar	No
22		Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	21.28	22.30	01.02		Tree fall on 11Kv line at Jawahar Nagar	No
23		Moula-Ali	Mirzalaguda	11KV	Sainikpuri	17.30	22.10	04.40		Tree faalen on 11Kv line at RFC Compound JTC Main Road	No
24		Moula-Ali	Moula-Ali	11KV	Sainikpuri	17.30	20.40	03.10		Polimer Disk fail at Rao Nagar Colony	No
25		Moula-Ali	Meerpet	11KV	Sainikpuri	22.17	23.35	01.18		Ground Petrolling done but no visible fount found	No
26		Pocharam	Pocharam	11KV	Keesara	17:35	18:05	0:30		11KV dend pole replaced at Pocharam village	No
1			Macha Bollarum	Ayyappa Nagar	11KV	C-VI	05.02	06.07	01.05	EL,OL-Rph	Brass Patti B/o at Sai Brindhavan Colony
2	Lalaguda		Nagarjuna Nagar	11KV	V	16:47	18:20	1:33	EL	No Visible Fault	No
3	Maitrivanam		Anand Bagh	11KV	IV	16:57	18:20	1:23	EL,OL-R&Bph	Tree branches fallen on lines at Anand Bagh	No
4	Maitrivanam		Srinivasa Colony (East)	11KV	IV	17:17	18:22	1:05	EL	Tree branches fallen on lines at Srinivasa Colony	No
5	Road No.22		M.C.R.	11KV	X	16.45	17.47	01.02	All Indication	No Visible Fault	No
6	Lalaguda		Vijaypuri	11KV	V	16.45	19.00	02.15	EL	Tree branches fallen on lines at Vijaypuri	No
7	Lalaguda		Shanthi Nagar	11KV	V	16:46	19:37	2:51	EL	Tree branches fallen on lines at Shanthi Nagar	No
8	I.D.P.L.		Saakshi	11KV	VI	16:42	18:05	1:23	EL,OL	Tree branches fallen on lines at Bala Nagar	No
9	I.D.P.L.		Bharath Nagar	11KV	IV	16:42	19:10	2:28	EL,OL-Rph	Tree branches fallen on lines at H.P.Road	No
10	I.D.P.L.		Oblum	11KV	VI	16.42	17.55	01.13	EL,OL-Yph	No Visible Fault	No
11	I.D.P.L.		Bala Nagar	11KV	VI	16.42	19.10	02.28	EL,OL	Tree branches fallen on lines at Shobhana Theatre	No
12	I.D.P.L.		SIFCO	11KV	VI	16.42	19.30	02.48	EL,OL	Tree branches fallen on lines at T.I.E. Bala Nagar	No
13	I.D.P.L.		S.V.C.I.E.	11KV	VI	16.42	17.55	01.13	EL,OL-Bph	No Visible Fault	No
14	I.D.P.L.		Shivalayam	11KV	VI	16:42	19:50	3:08	EL,OL-Yph	Banner fallen on lines at Sanath Nagar Flyover	No
15	H.P.S.		RBI Quarters	11KV	IV	17.00	18.40	01.40	EL	Tree branches fallen on lines at RBI Quarters	No
16	H.P.S.		Varun Towers	11KV	IV	17.00	19.30	02.30	EL	Tree branches fallen on lines at Varun Moters	No
17	Maitrivanam		Aditya Enclave	11KV	IV	17.38	18.55	01.17	EL	Iron touching to LT Line at Karanampuri Complex	No
18	Srinagar Colony		Kamalapuri Colony	11KV	X	16.54	18.17	01.23	EL,OL-Rph	No Visible Fault	No
19	R.P.Nilayam		Vaishnavi Matha	11KV	C-VI	16.30	17.48	01.18	EL,OL-Y&Bph	No Visible Fault	No
20	R.P.Nilayam		Alwal	11KV	C-VI	16.40	18.10	01.30	EL,OL-Rph	No Visible Fault	No
21	R.P.Nilayam		R.P.Nilayam Cable-2	11KV	C-VI	16.43	17.50	01.07	OL-Yph	No Visible Fault	No
22	R.P.Nilayam		Ram Nagar	11KV	C-VI	16.45	18.05	01.20	OL-R&Bph	No Visible Fault	No
23	R.P.Nilayam		Naga Devanna Temple	11KV	C-VI	16.38	17.48	01.10	EL	No Visible Fault	No
24	R.P.Nilayam		Saraswathi Nagar	11KV	C-VI	16.45	20.00	03.15	OL-Y&Bph	HT Conductor snapped at Madavaram	No
25	R.P.Nilayam		Venkatapuram	11KV	C-VI	16.43	19.20	02.37	EL	No Visible Fault	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
26	HYD N	Road No.12	Chiran Palace	11KV	X	16.57	18.35	01.38	EL,OL-Bph	Tree branches fallen on lines at Karur Vysya Bank	No
27		H.M.T	Sri Sai Colony	11KV	VI	17.00	19.50	02.50	EL	Tree branches fallen on lines at Sri Sai Colony	No
28		Allwyn	Crown Casting	11KV	IV	16.55	19.20	02.25	EL	No Visible Fault	No
29		Allwyn	Hanuman Temple	11KV	IV	16.40	18.20	01.40	EL	No Visible Fault	No
30		Allwyn	Indra Prasta	11KV	IV	16.50	18.30	01.40	EL,OL-Bph	No Visible Fault	No
31		Allwyn	E.S.I	11KV	IV	16.55	19.10	02.15	EL	No Visible Fault	No
32		Allwyn	Mothi Nagar	11KV	IV	16.55	18.10	01.15	EL,OL-Rph	No Visible Fault	No
33		Allwyn	Telephone Exg.	11KV	IV	16.25	19.40	03.15	EL	Tree branches fallen on lines at Czech Colony	No
34		Allwyn	I.E	11KV	IV	16.40	19.50	03.10	EL	No Visible Fault	No
35		Lodha	Hanuman Temple	11KV	IV	16.55	20.15	03.20	EL	Tree branches fallen on lines at various locations	No
36		Lodha	Crown Casting	11KV	IV	16.58	20.58	04.00	EL	Tree branches fallen on lines at various locations	No
37		Lodha	I.E	11KV	IV	16.50	21.02	04.12	EL	Tree branches fallen on lines at various locations	No
38		Osm. Univeristy	Mettuguda	11KV	V	17.00	19.50	02.50	EL	Tree branches fallen on lines at Mettuguda	No
39		Osm. Univeristy	RTC Hospital	11KV	V	17.00	19.50	02.50	EL	HT Jumper cut at O.U, Campus	No
40		Osm. Univeristy	Keshava Nagar	11KV	V	17.35	19.35	02.00	EL	No Visible Fault	No
41		Osm. Univeristy	Ravindra Ngaar	11KV	V	18.55	20.20	01.25	EL	Pin Insulator flash over at Model School	No
42		Lalaguda	Lalapet	11KV	V	16.45	20.15	03.30	EL	No Visible Fault	No
43		Lalaguda	St.Ann's	11KV	V	16.46	19.54	03.08	EL,OL	Tree branches fallen on lines at Pleasant Apts	No
44		Lalaguda	Chenna Reddy	11KV	V	16.46	20.08	03.22	EL	Tree branches fallen on lines at Canara Bank	No
45		H.A.L	Lokesh Machine	11KV	V	17.20	19.30	02.10	OL-Rph	No Visible Fault	No
46		Nehru Nagar	Contonment	11KV	C-VI	16.55	18.40	01.45	EL	Tree branches fallen on lines at Axis Bank	No
47		Addagutta	Addagutta	11KV	C-VI	16.53	20.58	04.05	EL,OL	Tree branches fallen on lines at Jyothi Colony	No
48		Bhudevi Nagar	Adarsh Nagar	11KV	C-VI	22.15	23.35	01.20	EL,OL	Tree branches fallen on lines at Adarsh Nagar	No
49		Toli Chowki	Road No.86	11KV	X	16.57	18.34	01.37	EL,OL-Y&Bph	No Visible Fault	No
50		E.S.I	IAS Quarters	11KV	IV	16.47	23.48	07.01	EL,OL-Bph	Tree branches fallen on lines at various locations	No
51		E.S.I	Bapu Nagar	11KV	IV	16.56	23.39	06.43	EL,OL-Rph	HT Jumper cut at Sai Krupa Apts	No
52		E.S.I	Czech Colony	11KV	IV	16.57	22.22	05.25	EL	Tree branches fallen on lines at Czech Colony	No
53		E.S.I	Municipal Park	11KV	IV	16.57	22.37	05.40	EL	Tree branches fallen on lines at Sriyamara Kunta Park	No
54		Bowenpally	Plassy Line	11KV	VI	16.42	17.45	01.03	EL,OL-Bph	No Visible Fault	No
55		Bowenpally	Pension Line	11KV	VI	16.43	18.28	01.45	EL,OL-R&Bph	No Visible Fault	No
56		Bowenpally	Pipe Line Road	11KV	VI	16.44	18.35	01.51	EL,OL-R&Bph	Tree branches fallen on lines at Pipe Line Road	No
57		Bowenpally	Akshaya Enclave	11KV	VI	16.24	18.55	02.31	EL,OL-R&Bph	Tree branches fallen on lines at Akshaya Enclave	No
58		Kalyan Nagar	Laxmi Nagar	11KV	X	16.55	19.10	02.15	EL	Lightning Arrestor failed at SS	No
59		Kalyan Nagar	A.G.Colony	11KV	X	16.55	19.18	02.23	EL,OL-Bph	Tree branches fallen on lines at A.G Colony Gate	No
60		Prashanth Nagar	Time Tek	11KV	VI	17.20	21.20	04.00	EL,OL	Tree branches fallen on lines at Time Tek	No
61		Prashanth Nagar	Ganesh Kanta	11KV	VI	17.45	20.20	02.35	EL,OL	Tree branches fallen on lines at Ganesh Kanta	No
62		Prashanth Nagar	Andhra Jyothi	11KV	VI	17.55	20.50	02.55	EL,OL-Rph	Tree branches fallen on lines at Spark Company	No
63		Prashanth Nagar	Colgate	11KV	VI	17.50	22.20	04.30	EL,OL-Rph	Tree branches fallen on lines at Bala Nagar	No
64		I.I.C.T	Solex	11KV	V	16.50	19.20	02.30	EL	Tree branches fallen on lines at Solex	No
65		I.I.C.T	Deccan	11KV	V	16.50	21.30	04.40	EL	Big tree fallen on lines at Nagarjuna Apts	No
66		I.I.C.T	Dal Mill	11KV	V	16.50	18.40	01.50	EL	Tree branches fallen on lines at Dal Mill	No
67		Macha Bollaram	Radha Sath Sang	11KV	C-VI	22.11	23.18	01.07	EL	No Visible Fault	No
68		R.P.Nilayam	E.M.E	11KV	C-VI	18.32	19.35	01.03	OL-Rph	No Visible Fault	No
69		Prakash Nagar	Majestic Mansion	11KV	IV	20.15	21.30	01.15	EL,OL	HT Service fault at Shoppers Stop	No
70		Lodha	Hanuman Temple	11KV	IV	21.48	00.23	02.35	EL	Tree branches fallen on lines at SBI Bank & TTI Line snapped	No
71		Toli Chowki	Road No.86	11KV	X	22.20	23.32	01.12	EL,OL-Yph	Tree branches fallen on lines at Road No.86	No
72		Bowenpally	Sancharapuri Colony	11KV	VI	22.25	23.32	01.07	EL,OL-Bph	No Visible Fault	No
73		Begumpet	D.K Road	11KV	IV	16.55	21.00	04.05	All Indication	Tree branches fallen on lines at D.K Road	No
74		Begumpet	H.P.S	11KV	IV	16.55	21.55	05.00	All Indication	Tree branches fallen on lines at H.P.S	No
75		Begumpet	Maitrivanam	11KV	IV	17.00	21.50	04.50	OL-R&Bph	Tree branches fallen on lines at Maitrivanam	No
76		Begumpet	ESI Staff Qrts	11KV	IV	17.10	20.45	03.35	EL,OL-Rph	Tree branches fallen on lines at ESI Staff Qrts	No
77		Begumpet	Shanthi Bagh	11KV	IV	17.15	22.05	04.50	All Indication	Tree branches fallen on lines at Shanthi Bagh	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	E.N.T.	E.N.T.	11KV	IX	17.02	19.52	02.50	EL	DTR structure fell down at Nakoda Complex	No
2		Kanchanbagh	Kanchanbagh	11KV	VIII	16.54	19.04	02.10	EL,OL-Rph	HT Jumper cut at Vysra Function Hall	No
3		Aliyabad	Sharada College	11KV	III	17.05	19.04	01.59	OL	HT Line snapped at Netaji School	No
4		Hyderguda	Jana Priya OH	11KV	III	17.00	20.50	03.50	EL	No Visible Fault	No
5		Hyderguda	A.G.Colony	11KV	III	17.00	20.05	03.05	EL	No Visible Fault	No
6		Hyderguda	W.S.Colony	11KV	III	17.00	19.30	02.30	EL	No Visible Fault	No
7		Hyderguda	Attapur	11KV	III	17.00	19.30	02.30	EL	No Visible Fault	No
8		Hyderguda	Hyderguda	11KV	III	17.00	19.58	02.58	EL	Tree branches fallen on lines at Hyderguda	No
9		Hyderguda	Jana Priya AB	11KV	III	16.49	19.30	02.41	EL	No Visible Fault	No
10		Panjasha	Pancha Mohalla	11KV	III	17.05	18.24	01.19	EL,OL	Cotton Cloth fallen on lines at Jama Masjid	No
11		Malakpet	Bibi Ka Alawa	11KV	III	17.05	18.50	01.45	EL	HT Jumper cut at Dabeerpura P.S	No
12		Malakpet	Yashoda Hospital	11KV	III	17.05	18.55	01.50	EL,OL-R&Yph	Foreign material fallen on lines at Naigonda X-Roads	No
13		Karwan	Jiaguda Cable	11KV	IX	17.01	19.25	02.24	EL	Disc Insulator flash over at S.D Garden	No
14		Karwan	R.S Temple	11KV	IX	17.04	21.25	04.21	OL-R&Bph	Disc Insulator flash over at Moghal Ka Nala	No
15		Falaknuma	Aliyabad	11KV	III	17.05	18.40	01.35	EL,OL-Bph	No Visible Fault	No
16		Falaknuma	Falaknuma OH	11KV	III	17.10	18.35	01.25	EL,OL-Bph	No Visible Fault	No
17		Falaknuma	Chatrinaka	11KV	III	17.10	18.50	01.40	EL,OL-Bph	No Visible Fault	No
18		Falaknuma	Jangammet AB	11KV	III	17.15	18.37	01.22	EL	No Visible Fault	No
19		Ch' Baradari	Doodbowli	11KV	III	17.04	19.28	02.24	EL	No Visible Fault	No
20		Salarjung	Q.Q Stadium	11KV	III	17.15	18.40	01.25	EL,OL-R&Bph	Pin Insulator flash over at City College	No
21		Miralam	Amzadullah Bagh	11KV	III	17.30	19.40	02.10	EL,OL-Rph	No Visible Fault	No
22		Miralam	Mustafa Nagar	11KV	III	17.55	20.15	02.20	EL,OL-Rph	DTR Lighting Arrestor failed at Azam Pan Shop	No
1	HYD C	Golnaka	Sai Madhura Nagar	11KV	II	01.51	03.39	01.48	OL	11KV Conductor snapped Opp Ramalayam FOC	No
2		Golconda	Darga Cable	11KV	VII	05.16	06.28	01.12	EL,OL-Rph	HT Conductor snapped at Indian Gas Godown	No
3		Nampally	Red Hills	11KV	VII	16.03	17.36	01.33	EL	No Visible Fault	No
4		Nampally	Yousufian Darga	11KV	VII	17.10	18.25	01.15	EL,OL	HT lines twisted at Tekdi Masjid	No
5		Langer House	Netaji Nagar	11KV	VII	17.00	18.20	01.20	EL	HT Pole fell down at Om Nagar (HT Pole kept off)	No
6		Narayangdua	Preventive Medicine	11KV	II	16.59	19.15	02.16	EL,OL-Rph	Deepak Theatre & Faulty 4No. DTR's Sai	No
7		S.D.Hospital	Humayun Nagar	11KV	VII	16.55	18.15	01.20	EL,OL-Bph	Tree branches fallen on lines at Ahmed Nagar	No
8		Vittalwadi	I.C.I.C.I Bank	11KV	I	17.05	18.14	01.09	EL,OL-R&Bph	No Visible Fault	No
9		A.C.Guards	N.M.D.C.	11KV	VII	19.10	20.38	01.28	OL-R&Bph	Tree branches fallen on lines at Hockey Ground	No
10		Asif Nagar	Kakatiya Nagar	11KV	VII	17.40	20.00	02.20	EL,OL-R&Bph	Line snapped at Mourne Bakery	No
11		Asif Nagar	Mehdipatnam OH	11KV	VII	17.25	19.50	02.25	EL	Banner fallen on lines at Pillar No.35	No
12		Asif Nagar	Jyothi Nagar	11KV	VII	17.03	20.15	03.12	All Indication	Tree branches fallen on lines & Jumper cut at Nandini Nagar Park	No
13		Asif Nagar	NSF Colony	11KV	VII	17.50	20.25	02.35	EL	Jumper cut at Baba Dairy Form	No
14		A.S.R.Raju Nagar	LIC Office	11KV	VII	17.02	18.54	01.52	EL,OL	Tree branches fallen on lines at LIC Office	No
15		Karwan	Langer House OH	11KV	VII	17.01	18.40	01.39	EL,OL-Rph	No Visible Fault	No
16		Karwan	Langer House UG	11KV	VII	17.04	18.45	01.41	OL-Rph	No Visible Fault	No
17		Gudi Malkapur	Amba Garden	11KV	VII	17.46	19.12	01.26	EL	No Visible Fault	No
18		Gudi Malkapur	Navodaya Colony	11KV	VII	17.24	19.56	02.32	EL,OL	Lugs burntout at Opp: SS	No
19		Mothi Mahal	Balansar	11KV	VII	17.03	18.22	01.19	EL,OL-R&Yph	No Visible Fault	No
20		Mothi Mahal	M.D Lines	11KV	VII	17.01	19.46	02.45	EL,OL-R&Yph	Tree branches fallen on lines at 3 Darga	No
21		Industrial Area	RTC X-Roads	11KV	II	17.50	19.30	01.40	All Indication	Tree branches fallen on lines at Bus Bhavan	No
22		Industrial Area	Barkathpura	11KV	II	16.45	18.45	02.00	EL,OL-Bph	No Visible Fault	No
23		Industrial Area	Vidya Nagar	11KV	II	16.55	19.30	02.35	EL	Tree branches fallen on lines at Vidya Nagar	No
24		Nampally	Nampally Hospital	11KV	VII	17.09	18.50	01.41	EL	Tree branches fallen on lines at Nampally Hospital	No
25		Toli Chowki	Kala Banglow	11KV	VII	16.53	19.09	02.16	EL,OL-Rph	No Visible Fault	No
26		Toli Chowki	B.S.N.L	11KV	VII	17.00	18.16	01.16	EL,OL-Y&Bph	No Visible Fault	No
27		Toli Chowki	Para Mount Hills	11KV	VII	17.09	19.25	02.16	EL,OL-Yph	No Visible Fault	No
28		Toli Chowki	Hakeemsha	11KV	VII	17.48	19.50	02.02	OL-Y&Bph	No Visible Fault	No
29		Fever Hospital	Tourist Hotel	11KV	II	17.00	19.00	02.00	All Indication	Tree branches fallen on lines at Tourist Hotel	No



S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
30		Fever Hospital	C.C Shroff Hospital	11KV	II	18.52	21.10	02.18	All Indication	Tree branches fallen on lines at Bhumanna Gally	No
31		Fever Hospital	Barkatpura Bus	11KV	II	16.52	18.14	01.22	All Indication	Tree branches fallen on lines at Barkatpura Bus	No
32		Fever Hospital	Barkatpura Bus Depot	11KV	II	18.22	20.50	02.28	All Indication	Tree branches fallen on lines at Barkatpura Bus Depot	No
33		Fever Hospital	Fever Hospital	11KV	II	16.50	19.15	02.25	All Indication	Tree branches fallen on lines at B.S.N.L Office	No
34		Fever Hospital	Sri Ram Nagar	11KV	II	16.47	19.00	02.13	All Indication	Tree branches fallen on lines at Anjaiah Quarters	No
35		Bathkammakunta	Ahobilmutt	11KV	II	16.58	18.55	01.57	OL-Bph	Tree branches fallen on lines at Azam House	No
36		Bathkammakunta	D.D Colony	11KV	II	16.58	19.05	02.07	EL,OL-Rph	Gun insulator flash over near Meena Kumari House	No
37		Toli Chowki	Kala Banglow	11KV	VII	22.37	23.58	01.21	EL,OL	HT Jumper & Brass Patti cut at Maqbool PT	No
38		Golconda	Darga OH	11KV	VII	17.04	18.22	01.18	EL,OL-Rph	No Visible Fault	No
39		Golconda	O.U Colony	11KV	VII	17.14	18.24	01.10	EL,OL-Rph	No Visible Fault	No
40		A.S.R.Raju Nagar	Sai Garden	11KV	VII	23.05	03.52	04.47	OL	Due to rain	Arranged B/F on 11KV Amba Garden feeder