

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933	2	0	2	0	2	0			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	11	3	11	3	11	0	0	
	Grand Total	1082	6468	3	11	3	11	3	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	09.40	16.20	06.40		33KV Insulator failed at Rayapuram, H/o.Inupamula(V)	Aitipamula	No
1	MDK	Sadasivpet	Koheer	33KV	Sangareddy	14.35	19.25	04.50		BD due to Pin Binding failed	Sadasivpet	Alternate supply arranged for 33KV Jharasangem feeder fro 132KV ZHB
2		Sadasivpet	Kondapur	33KV	Sangareddy	15.05	16.20	01.15		BD due to Jumper cut	Sadasivpet	No

TSSPDCL - LMRC / Corporate office

Date: 11.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nawabpet	Kondapur	11KV	Jadcherla	06.40	08.47	02.07		11 KV insulater fail near Hazilapoor.	-
2		Janampet	Polkampally	11KV	Jadcherla	00.00	06.10	06.10		11 KV insulater fail near Polkampally.	-
1	NLG	Cheedella	Gajula malkapuram	11KV	Suryapet	07.30	09.00	01.30	E/L	Insulator Flashover	-
2		Dirincherla	Yallapuram	11KV	Huzurnagar	08.20	11.00	02.40	EL	11 KV LINE TREE FALLEN	-
3		Thogarrai	Kuchipudi	11KV	Huzurnagar	12.20	14.10	01.50	EL	11 KV LINE SNAPPED	-
4		Rajupeta	Bandavarigudem	11KV	Nalgonda	09.00	12.05	03.05	EL	11KV line melting at Railway track Bandavarigudem	-
5		Baironibanda	N.G.Kothapally	11KV	Nalgonda	16.13	18.00	01.47	EL	11KV jumper cut	-
6		Paladugu	Dattappagudem	11KV	Bhongir	13.20	16.00	02.40	OL	11 KV Jumper Cut Near Podichedu Village	-
7		Laxmi devigudem	Ravula penta	11KV	Miryalaguda	13.10	15.05	01.55	EL	Insulator Failed	-
8		Rajavaram	Rajavaram	11KV	Miryalaguda	10.45	18.00	07.15	EL	Insulator Failed	-
1	SDPT	Dhoolmitta	Arjunpatla	11KV	Husnabad	11.06	12.50	01.44		Insulator failed same rectified	