

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933		2		2		2			
4	SDPT				11		11		11			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	21	1	21	1	21	0	0	
	Grand Total	1082	6468	2	27	2	27	2	27	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.06.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Mutyalanagar	Burugadda	33KV	Huzurnagar	13:43	14:50	1:07	EL/OL	33kv line snapped	Burugadda	No
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	14:40	15:55	1:15		33KV Cable Jumper cut & replacement at Dulapally	Kompally	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	B.Chandupatla	Thimmapuram	11KV	Suryapet	14:30	16:00	01.30	E/L	Tree branch fallen on the line	No
2		Urlugonda	Tummagudem	11KV	Huzurnagar	03.00	05.30	02.30	E/L	11KV line snapped	No
3		Urlugonda	Express	11KV	Huzurnagar	03.30	06.00	02.30	E/L	11KV line snapped	No
4		Repala	Repala	11KV	Huzurnagar	06.00	09.30	03.30	E/L	11KV Jumper Cut	No
5		Seethya Thanda	Seethya Thanda	11KV	Miryalguda	08.40	08.58	00.18	E/L	11KV Jumper Cut	No
6		Pulicherla	Pulicherla	11KV	Miryalguda	14.25	16.30	02.05	E/L	11KV Jumper Cut	No
7		Thimmapuram(Ramadugu)	Thimmapuram	11KV	Miryalguda	10.00	13.00	03.00	E/L	11KV Jumper Cut	No
8		Rajavaram	Tirumalagiri	11KV	Miryalguda	04.30	06.30	02.00	E/L	11KV Jumper Cut	No
1	MDK	Fasalwadi	MNR	11KV	Sangareddy	15:51	16:38	00.47		Tree fallen on 11KV line at Petrol bunk	No
2		Gaddapotharam - I	Kekule	11KV	Patancheru	20.15	22.45	02.30		Insulator failed	No
1	SDPT	Bejanki	Kallepally	11KV	Husnabad	12:45	14:00	01.15		Insulator failed	No
2		Regulapally	Mallamchervu	11KV	Husnabad	10.00	15.30	05.30		Disc failure	No
3		Regulapally	Regulapally	11KV	Husnabad	08.00	13.02	05.02		Jumper cut	No
4		Komuravelly	Kadaveru	11KV	Husnabad	18.45	19.15	00.30		Insulator failed	No
5		Komuravelly	Kistampet	11KV	Husnabad	14.45	16.15	01.30		Jumper cut	No
6		Nagapuri	Nagapuri	11KV	Husnabad	19.00	20.20	01.20		Conductor snapped	No
7		Nagapuri	Pothireddypalli	11KV	Husnabad	14.05	15.00	00.55		Conductor snapped	No
8		Koheda	Kurella	11KV	Husnabad	13.10	14.50	01.40		Conductor snapped	No
9		Koheda	Sriramulapally	11KV	Husnabad	13.45	15.00	01.15		Conductor snapped	No
10		Koheda	Theegalakuntapally	11KV	Husnabad	13.25	15.20	01.55		Conductor snapped	No
11		Ramchandrapur	Vinjalpally	11KV	Husnabad	15.30	16.00	00.30		Insulator failed	No
1	RR N	Ravalkole	IDA Ganapathi	11KV	Medchal	11:03	12:40	01.37		11KV Pin Insulator failed at Rotech Crusher	No
2		DPPally	Gagillapur	11KV	Jeedimetla	16.10	20.50	04.40		HT/LT line fallen the 11KV line at Sundhara Chaithaya Ashram & Gagillapur	No
1	RR E	Sainikpuri	Sainikpuri	11KV	Sainikpuri	5:07	6:05	0:58		Tree fallen on the 11KV line at Sainikpuri	No
1	HYD N	Zamistanpur	S.P.College	11KV	Sec'bad	18.26	19.34	01.08	EL,OL	Faulty 3No. DTR's at S.P.College	No
2		Monda Market	Monda Market	11KV	Sec'bad	19:02	20:40	1:38	All Indication	Pin Insulator flash over at Islamiya School	No
1	HYD C	Amberpet	6No. Road	11KV	Azamabad	18.10	20.00	01.50	All Indication	Conductor snapped & tree branches fallen on lines at Bata Show Room	No