

TSSPDCL - LMRC / Corporate office

Date: 01.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD S				NIL							-
8	HYD N				NIL							-
9	HYD C				NIL							-

TSSPDCL - LMRC / Corporate office

Date: 01.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Town	11kv	Jadcherla	08.55	11.55	03.00		11 Line Cut Near Rajapur(Vi).	-
1	NLG	Mupparam	Lift	11kv	Mirylaguda	09.00	09.45	00.45	EL	11KV disc failed	-
2		Agamothkur	Chirumarthy	11kv	Mirylaguda	09.58	13.15	03.17	EL	11KV conductor snapped	-
3		Kamareddygudem	Poosalaphad	11kv	Mirylaguda	01.57	08.30	06.33	EL	S-Ph supply OK, 3-ph breakdown	-
4		Nagaram	N S Gudem	11kv	Suryapet	06.30	09.00	02.30	EL	Jumper cut	-
5		Raghunadapalem	Gundlapally	11kv	Huzurnagar	19.10	21.15	02.05	EL	Due to tree branch fall on 11Kv line	-
6		Ananthagiri	Shantinagar	11kv	Huzurnagar	08.30	12.00	03.30	EL	Due 11Kv Disk failure	
7		Timmareddy gudem	Ganapavaram	11kv	Huzurnagar	04.45	07.55	03.10	EL	Due to 11Kv Jumper cutted	
8		Addagudur	CH.Ramaram	11kv	Bhongir	09.50	10.50	01.00	EL	Jumper cut Near CH.Ramaram Village	-
9		Vemulakonda	Goparajupally	11kv	Choutuppal	13.35	16.45	03.10	EL	11kv Line Burnt Near Goparajupally Village	-
1	MDK	GANDIPALLY	GANDIPALLY	11kv	Husnabad	17.50	23.50	06.00		BD 3 Ph,(SPH OK)	-
1	RR E	IDAuppal	Metro	11kv	Habsiguda	05.30	06.00	00.30		Lorry dashed to 11kv pole at RN filter Idauppal	-
1	HYD S	E.N.T.	Gurudwara	11kv	IX	23.50	01.00	01.10	All Indication	No Visible Fault	