

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	9	1	9	1	9	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Munipally	33KV	Sangareddy	14.45	15.35	00.50		BD Due to Jumper cut at MRF Company	Munipally	-

TSSPDCL - LMRC / Corporate office

Date: 04.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pajjur	Kaziramaram	11KV	Nalgonda	09.30	11.40	02.10	E/L	11 KV Line Disc Failure	-
2		Chandur	Gundrepally	11KV	Nalgonda	10.26	13.02	02.36	E/L	11 KV Line Insulator Failed	-
3		Neelalyagudem	Neelalyagudem	11KV	Miryaguda	07.30	08.47	01.17	E/L	11 KV Jumper cut at near village	-
4		Alingapuram	Gundlapahad	11KV	Huzurnagar	07.30	09.30	02.00	E/L	11 KV LINE SNAPPED	-
5		Nadigudem	Brundavanapuram	11KV	Huzurnagar	05.00	08.20	03.20	E/L	3 phase Transformer failed	-
6		Motakondur	Vattoor	11KV	Bhongir	14.00	15.20	01.20	E/L	11kv Line Snapped at Vattoor Villge	-
1	MDK	Kistareddypet	Industrial	11KV	Patancheru	11.30	12.50	01.20		BD Due to Conductor Snapped at Bhudanam (v)	-
2	SDPT	Dharmaram	Nandaram	11KV	Husnabad	12.10	14.10	02.00		11KV Conductor snapped	-
3		Pandilla	Kunchanpally	11KV	Husnabad	17.00	18.45	01.45		Conductor snapped	-
1	RR N	Ravalkole	IDA Ganapathi	11KV	Medchal	07.30	09.55	02.25	BD	Bird fallen on the 11KV Line at Rajabollaram Thanda	-
1	RR E	Cherelapally-I	Phase-I	11KV	SKP	02.35	04.30	01.55		Net cable shoted and touched 11Kv line at Ganesh Winding (LM Kashi Ram)	-