

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	3	1	3	1	3	0	0	
	Grand Total	1082	6468	1	4	1	4	1	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.03.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Kandi	Sangareddy - II	33KV	Sangareddy	12:10	12:45	0:35		Conductor snapped at Ismailkhanpet	Sangareddy - II	No

TSSPDCL - LMRC / Corporate office

Date: 12.03.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nuthanakal	Yerrapahad	11KV	Suryapeta	6:50	9:00	2:10	E/L	Insulator failed	No
2		Eduloor	Naragudem	11KV	Nalgonda	13.00	16.00	03.00	E/L	11KV Jumper cut	No
3		Madgulapally	Kukkadam	11KV	Nalgonda	09.20	12.10	02.50	E/L	11KV Disc failed	No
1	RR N	Aliabad	LGM Pet	11KV	Medchal	16:30	18:30	2:00		100KVA DTR Brass patti cut at Mallanna Temple LGM Pet	No