

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		8		8		8			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	1	12	1	12	1	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.03.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD S	220KV Shivrampally	Attapur	33KV	Malaket	07.05	07.23	00.18	EL,OL-Rph	UG Cable damaged by unknown person at PVNR highway, Pillar No.224	Attapur	Loads transferred onto 220KV Shivrampally SS via 33KV Ch' Baradari OH fdr

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kandoor	Komreddipally	11KV	Jadcherla	04.20	07.26	03.06		11KV Insulator failed near Komireddy Pally	No
1	NLG	Gaddipaly	Ponugodu	11KV	Huzurnagar	05.45	09.00	03.15	E/L	Tree branch fallen on the 11KV line	No
2		Gondriyala	Gondriyala 02	11KV	Huzurnagar	06.15	09.10	02.55	O/L	11KV Line snapped	No
3		Gondriyala	Chimiryala	11KV	Huzurnagar	05.10	08.00	02.50	O/L	11KV Line snapped	No
4		Thogarrai	Ganapavaram	11KV	Huzurnagar	05.30	08.30	03.00	E/L	Tree branch fallen on the 11KV line	No
5		Motakondur	Motakondur	11KV	Bhongir	08.45	10.45	02.00	E/L	HT/LT Near Motakondur Village	No
6		Bollepally	Surepally	11KV	Bhongir	12.20	12.40	00.20	E/L	11KV Jumper open near Sureypally (V)	No
7		B.Ramaram	Town	11KV	Bhongir	08.15	08.40	00.25	E/L	Bird fallen & 11KV Line snapped at near High School	No
8		Alair 2	Alair Agl	11KV	Bhongir	13:02	17:02	03.00	E/L	11KV Line Snapped near Alair (V)	No
1	RR N	Jeedimetla-II	Phase-II	11KV	Medchal	06.00	08.26	02.26	EL/OL	11KV Line AB Cable failed near Samatha Wires at Phase-I	No
2		Kompally	Kompally	11KV	Medchal	17.18	18.13	00.55		11KV Cable End Kit failed at Bagireddy Function Hall	No
1	RR E	Aushapur	Aushapur	11KV	Keesara	16:00	19:00	3:00		11KV Line melted	No