

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 16.03.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Buddaram	33KV	Wanaparthy	17.58	20.55	02.57		PTR's Pull out	Buddaram	Alernate supply Given to 132KV SS Nagarkurnool at 20:55 hrs
2		Wanaparthy	Goplapet	33KV	Wanaparthy	17.58	20.55	02.57		PTR's Pull out	Goplapet	Alernate supply Given to 132KV SS Nagarkurnool at 20:55 hrs
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	17:20	18:50	1:30		33KV Jumper cut and replaced at Medchal Checkpost	33KV Medchal-I	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	S V College	Loyala AGL	11KV	Suryapet	13:30	15:00	1:30	E/L	11KV Jumper cut	No
2		Mattapally	Mattapally town	11KV	Huzurnagar	14.45	16.15	02.30	E/L	11KV Line Snapped	No
3		Thogarrai	Kapugallu	11KV	Huzurnagar	12.20	13.50	01.30	E/L	11KV Line Snapped	No
4		Chandampeta	GaJilapur	11KV	Devarakonda	04.00	07.00	03.00	O/L	HT/LT	No
5		Neredugommu	SLBC	11KV	Devarakonda	10.00	11.00	01.00	E/L	Tree fallen on the 11KV line	No
6		Chada	Nancharipet	11KV	Bhongir	10.40	12.40	02.00	E/L	11KV Insulator failed in Nancharipet Village	No
7		Mandollagudam	Mandollagudam Agl	11KV	Choutuppal	11:00	12:10	1:10	E/L	11KV Line snapped near Mandollagudem Village	No
1	RR N	Subhash Nagar	Meenakshi	11KV	Medchal	16:34	17:15	0:41		11KV Brass Patti cut and replaced at Narasingh Shop	No