

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Date: 22.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Keethavarigudem	Velidanda	11KV	Huzurnagar	05.30	08.00	02.30	EL	11KV Jumper Cut	-
2		Chada	Chada	11KV	Bhongiri	06.00	10.45	04.45	EL	11 KV Insulator Fail at Kurella Murali Well Near Chada Village	-
3		Manaikunta	Manaikunta	11KV	Bhongiri	08.30	11.00	02.30	OL	25 Kva DTR Fail Rice Mill Back Side Near Manaikunta Village	-
4		Paladugu	Duppelly	11KV	Bhongiri	16.15	16.40	00.25	OL	11 kv Jumper Cut at Yerra Canal Near Duppelly Village	-
5		Madgulapally	Kukadam	11KV	Nalgonda	09.00	10.30	01.30	EL	11 KV Jumper Cut	-
6		Nemmani	Poothinenipally	11KV	Nalgonda	15.00	16.00	01.00	EL	11 KV Jumper Cut	-
1	RR S	MD Pally	Laxmiguda	11KV	RJNR	10.00	11.00	01.00	B/D	11kv Cable Failed at Laxmiguda Temple	-